State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

FILE IN TRIPLICATE	OIL CONSERVA	TION I	DIVISION				
DISTRICT I	2040 Pacheco St. Santa Fe, NM 87505			WELL API NO.			
P.O. Box 1980, Hobbs, NM 88240				30-025-35450			
<u>DISTRICT II</u>				5. Indicate T	ype of Lease STATE	X FEE	
811 S. 1st Street, Artesia, NM 88210					& Gas Lease No.	A ILL	\dashv
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410				o. State on	a Gus Ecuse 110.		
SUNDRY NOTICES AND REPORTS ON WELLS							
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			NORTH HORRE (C/CA) UNIT				
(FORM C-101 FOR SUCH PROPOSALS.)				NORTH HOBBS (G/SA) UNIT			
1. Type of Well: Oil Well X Gas	Well Other						
2. Name of Operator		,,,,,		8. Well No.	612		į
Occidental Permian Ltd.				9. Pool name	e or Wildcat	HOBBS (G/SA)	-
3. Address of Operator 1017 W. Stanolind Rd., HOBBS, NM 88240	505/397-	-8200		<i>y.</i> 1 001 ham	or Wildea	HODDS (G/S/V)	
4. Well Location				•			
Unit Letter E : 2220 Feet Fr	om The NORTH L	ine and	406 Fee	et From The	WEST	Line	
		•	275	N.I.	MPM	LEA County	
Section 24	Township 18S vation (Show whether DF, RKB		Range 37E	, 181	VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	LEA County	7
3676'		, KI OA, C	,				
11. Check Appropri	iate Box to Indicate Natu	ire of Not	ice, Report, or 0	Other Data			
NOTICE OF INTENTION	TO:		SUB:	SEQUENT	REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK					ALTERING (CASING	
TEMPORARILY ABANDON CHANG	CHANGE PLANS COMMENCE DRILLING OPI			NS.	PLUG & AB	ANDONMENT [
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB					
OTHER:		OTHER:	NEW WELL C	OMPLETION		<u> </u>	X
12. Describe Proposed or Completed Operations (Clearly	state all pertinent details, and	give pertine	nt dates, including	estimated date	of starting any prope	osed work)	
SEE RULE 1103.	•						
1. RUPU. RU Star Tool and Drill out DV Too	J @3511'						
1. RUPU. RU Star Tool and Drill out DV 100 2. Clean out to PBTD @4390'.							
3. Perforate 4216-4327.					100000		
4. RU Halliburton and Acidize w/500 g 15% I5. RIH w/REDA ESP production equipment of	HCL. n 134 its 2-7/8" tha				K.		
5. RIH w/REDA ESP production equipment of	11 134 jts 2-7/6 tog.			(6)	1 00		
Bottom of tbg @4139'.					11/1/1/2)	
Well producing 01/03/2002				1	144 15		
Rig Up Date: 12/26/2001				\;	4 45.00)	
Rig Down Date: 01/03/2002					, . 65		
					in the second second		
I hereby certify that the information above is true and cor	aplete to the best of my knowle	dge and bel	ief.				
SIGNATURE Tobut Filler	-	TITLE	SR. ENGR. TE	СН	DATE	01/15/2002	
TYPE OR PRINT NAME ROBERT GILBERT		•			TELEPHONE NO.	505/397-8206	
(This space for State Use)							_
(This space for state Ose)			ا برداره سرم	SHGMED BY			
APPROVED BY		TITLE		KAUTZ	—— FEB	1 5 2002	
CONDITIONS OF APPROVAL IF ANY:				A ENGINE	R		