

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-104A

March 19, 2001

Oil Conservation Division
220 South St. Francis Dr.
Santa Fe, NM 87505Submit 1 copy of the final affected wells
list along with 1 copy of this form per
number of wells on that list to appropriate
District Office**Change of Operator****Previous Operator Information:****New Operator Information:**OGRID: 017643
Name: Phillips Petroleum Company
Address: 4001 Penbrook Street
Address: _____
City, State, Zip: Odessa, TX 79762Effective Date: 01/01/2003
New Ogrid: 217817
New Name: ConocoPhillips Company
Address: 4001 Penbrook Street
Address: _____
City, State, Zip: Odessa, TX 79762

I hereby certify that the rules of the Oil Conservation Division have been complied with and that the information on this form and the attached list of wells is true and complete to the best of my knowledge and belief.

New Operator

Signature: Yolanda PerezPrinted name: Yolanda PerezTitle: Sr. Regulatory AnalystDate: 12/30/2002 Phone: (832)486-2329

Previous operator complete below:

Previous

Operator: Phillips Petroleum Company

Previous

OGRID: 017643Signature: Steve de Albuquerque

Printed

Name: Steve de Albuquerque**NMOCD Approval**Signature: Paul F. Kautz

Printed

Name: PAUL F. KAUTZDistrict: PETROLEUM ENGINEERDate: JAN 27 2003

WELLS INVOLVED IN OPERATOR CHANGE
FINAL LIST WITH C-104A

DEC 31, 2002

ing transferred. If all bonding requirements
to the OCD District with your C-104A.

217817 ConocoPhillips Co

IPS PETROLEUM CO

NEW OPERATOR:

ULSTR	OCD UNIT	LTR	AP1	WELL TYPE	POOL ID	POOL NAME	LAST PROD/INJ
P-23-17S-33E	P		30-025-30481	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
L-23-17S-33E	L		30-025-01515	O	37810	LEAMEX; PENN	09-2002
P-23-17S-33E	P		30-025-01516	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
D-24-17S-33E	D		30-025-26420	I	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 11-2001
F-24-17S-33E	F		30-025-26423	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
B-24-17S-33E	B		30-025-26850	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
J-24-17S-33E	J		30-025-26851	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
L-24-17S-33E	L		30-025-26852	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
N-24-17S-33E	N		30-025-27650	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
P-24-17S-33E	P		30-025-27651	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
H-24-17S-33E	H		30-025-27652	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
O-24-17S-33E	O		30-025-35570	I	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
M-24-17S-33E	M		30-025-35571	I	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
K-24-17S-33E	K		30-025-35572	I	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
E-24-17S-33E	E		30-025-35575	I	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
B-25-17S-33E	B		30-025-29115	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 03-1997
H-25-17S-33E	H		30-025-29116	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 07-1994
P-25-17S-33E	P		30-025-30096	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 10-2001
N-25-17S-33E	N		30-025-30097	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 01-1999
L-25-17S-33E	L		30-025-30448	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 10-2001
J-25-17S-33E	J		30-025-30449	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
D-25-17S-33E	D		30-025-30467	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
F-25-17S-33E	F		30-025-30453	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
C-25-17S-33E	C		30-025-35573	I	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
B-26-17S-33E	B		30-025-20516	I	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
M-26-17S-33E	M		30-025-27764	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 03-1997
P-26-17S-33E	P		30-025-30067	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
L-26-17S-33E	L		30-025-30069	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 07-2002
F-26-17S-33E	F		30-025-30070	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 07-1994
H-26-17S-33E	H		30-025-30071	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002
N-26-17S-33E	N		30-025-30394	O	43329	MALJAMAR; GRAYBURG-SAN	ANDRES 09-2002