

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.

30-025-35743

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Occidental Permian Limited Partnership

3. Address of Operator

P.O. Box 4294, Houston, TX 77210-4294

8. Well No.

843

9. Pool name or Wildcat

Hobbs; Grayburg - San Andres

4. Well Location

SH: Unit Letter **I** : **1933** Feet From The **South** Line and **294** Feet From The **East** Line
BH: **I** **1409** **South** **740** **East**
Section **33** Township **18-S** Range **38-E** NMPM **Lea** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3627' GL

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: **Rm 7" Casing** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/4/02 -

1/5/02: **Rm 111 jts. 7", 23#, J-55, LT&C casing with 12 centralizers and set at 4448'. Cement first stage with 250 sx. Premium Plus. Bump plug, drop bomb, and open DV tool. Circulate 127 sx. to surface. Cement second stage with 600 sx. Interfill 'C' and 100 sx. Premium Plus. Plug down and circulate 200 sx. to surface. Nipple down x set slips x rig down.**

Release drilling rig at 5:30 p.m., 1/5/02.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Stephens

TITLE Business Analyst (SG)

DATE 1/7/02

TYPE OR PRINT NAME Mark Stephens

TELEPHONE NO. 281/552-1158

(This space for State Use)

APPROVED BY

TITLE

PAUL F. ...
PETROLEUM ENGINEER

JAN 15 2002

CONDITIONS OF APPROVAL, IF ANY: