

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. JM. 01371
Unit M

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	<input checked="" type="checkbox"/>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

..... July 16, 1951, 19__

Edwards
Well No. 1 is located 600 ft. from TXK line and 600 ft. from TXK line of sec. 22
SW1/4 Sec. 22 18S 32E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3759 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

As per conversation with Mr. Jack Frost set a 20 sack cement plug from 2400 to 2550 leaving 43 feet of cement in 8 5/8" pipe. Set 20 sack cement plug from 1115 to 1155 after recovering 1803 feet of 8 5/8". Then pulled ~~299~~ feet of 10 3/4". 20 sack cement plug placed at the surface and erected customary marker. All intervals between plugs from surface to total depth left full of mud. Weight 0.5. Work done by Denton Oil Well Cementing Co. on July 10 1951
Abandoned at 6200'. Drill stem test indicated dry hole.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Oil Associates, Inc.
R. T. Wilson
Address 913 S. Third
Artesia N.M.
By _____
Title Superintendent