

DISTRICT I
1625 N. French Dr., Hobbs, NM 88240
DISTRICT II
811 South First, Artesia NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410
DISTRICT IV
2040 South Pacheco, Sante Fe, NM 87505

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-02065

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.
B-2354

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:
Oil Well Gas Well Other **Injection**

2. Name of Operator
Mobil Producing TX. & N.M. Inc.

3. Address of Operator **P.O. Box 4358
Houston TX 77210-4358**

4. Well Location
Unit Letter **P** : **660** Feet From The **south** Line and **660** Feet From The **east** Line
Section **22** Township **17S** Range **34E** NMPH **Lea** County

7. Lease Name or Unit Agreement Name
State II

8. Well No.
1

9. Pool name or Wildcat
Vacuum; Grayburg-San Andres

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

| | | | |
|--|--|---|---|
| NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/> | SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: Temporarily Abandon <input checked="" type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> PLUG & ABANDONMENT <input type="checkbox"/> |
|--|--|---|---|

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. (For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion)

7/22/02 Rig up WSU. Took head off pump jack beam. Bled well down, unseated pump. Laid down polish rod, subs, pump and gas anchor. Changed to tubing equipment. Closed well in.

7/23/02 Bled well down. Unflanged wellhead. Installed screw-on flange, spool and BOP. POOH with 148 jts 2-7/8", SN, perf'ed sub and mud anchor. Tallied out of hole. Laid down 16 bad jts. RU WLU. RIH w/ gauge ring to 4400'. POOH w/ gauge ring. RIH w/ CIBP, set at 4408'. RIH w/ cement bailer, dumped 35' cement on top of CIBP. POOH w/ bailer. RD WLU. RIH w/ 30 jts 2-7/8", closed BOP. SIFN.

7/24/02 Bled well down. RIH w/ 132 jts 2-7/8". RU pump truck to casing, closed BOP. Loaded hole and pressured up to 500 psi, lost 300 psi in 7 min. Pressured up to 500 psi a second time, lost 300 psi in 7 min. Stood 10 jts back in derrick. Laid down 122 jts. Picked up 5-1/2" packer, SN and 30 jts 2-7/8" tubing, tallied back in hole. SIFN

7/25/02 Bled well down. PU 140 jts 2-7/8" tubing w/ SN and 5-1/2" packer. RU pump truck. Started hunting for casing leak. Found hole between 8' and 11' from surface. Took off packer. RIH w/ 30 jts 2-7/8" for kill string.

7/26/02 Serviced rig. RDMO WSU.

7/29/02 Dug out wellhead and installed tin horn. Back fill. Set rig mats.

SEE ATTACHMENT FOR ADDITIONAL REMARKS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tiffany Stebbins TITLE Staff Office Assistant DATE 08/23/2002

TYPE OR PRINT NAME Tiffany A. Stebbins TELEPHONE NO. (713) 431-1207

(This space for State Use)

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL IF ANY:

ORIGINAL SIGNED BY
GARY W. WINK
OC FIELD REPRESENTATIVE II/STAFF MANAGER

AUG 28 2002

This Approval of Temporary
Abandonment Expires 8/26/07