DI	TRIBUTION			
SANTA FE				
FILE				NI
U.S.G.S.				L.I.
LAND OFFICE				
TRANSPORTER	OIL			
	GAS	}	1	
PRORATION OFFIC	E			
OPERATOR				

3

÷

EW 1	MEXICO	OIL	CONSERVATION	COMMISSION.
------	--------	-----	--------------	-------------

Santa Fe, New Mexico

## **MISCELLANEOUS NOTICES**

HOZBS OFFICE O. C. C. MAN 7 10 43 AM 64

(Form C-102) (Revised 7/1/52)

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which while e given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

## Indicate Nature of Notice by Checking Below

Notice of Intention to Change Plans	Notice of Intention to Temporarily Abandon Weli	L.	Notice of Intention to Drill Deeper	N	
NOTICE OF INTENTION TO PLUG WELL	Notice of Intention to Plug Back		Notice of Intention to Set Liner	N	
Notice of Intention to Squeeze	Notice of Intention to Acidize		Notice of Intention to Shoot (Nitro)	N	
Notice of Intention to Gun Perforate	Notice of Intention (Other)	x	Notice of Intention (Other)	4	
OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO	N Roswell, New	Mexico	January 6,	1964	
Gentlemen:				(1417)	
Following is a Notice of Intention t	o do certain work as described below	v at the			
Shell Oil Company	State "G	n		. Р	
SE SE (Company or Open 1/4 SE 1/4 of Sec	rator)	150 R			•••••
(40-acre Subdivision)	, T. 41-0, R. 54-	.,NMPM.,	Vacuum	•••••••••••••••••••••••••••••••••••••••	.Pool
	.County.				
F	ULL DETAILS OF PROPOSE	D PLAN O	FWORK		
(FOLL	OW INSTRUCTIONS IN THE R	ULES AND F	EGULATIONS)		
ABANDON GRAYBURG-SAN ANDR	ES AND TEST YATES				
1. Pull rods, pump and t	ubing.				
2. Set CIBP at 43001 and 3. Perforate with one 3/	Cap with cement.				
3065', 3066', 3067',	8" jet shot at 3022', 3 3068', 3083', 3084', 30 3135', 3136', 3139', 21	0231, 302	51, 30261, 30301	, 3031', 3032	t,
	J#JJ   J#JU'   J_J]			3109', 3110'	,
4. Kun tubing with packe	r and set packer at ann	roximatel	20501		
2. Treat below packer wi	th 6000 gallons 15% NEA	in 7 stag	ges with Fe addi	tive and ball	
sealers. 6. Swab test.					
•	end upon results of tes	•			
	and upon results of tes	<b>U</b> .			
1 (1 <b>54</b>					
.* .		<b>0</b> 1	-		
Approved Except as follows:	, 19	Shell 011	Company or Gradinal	O the state	
-	Ву	R. A. Low	ery <b>B. A.</b> 1	Lowrey	
	dy				

	By
Approx	Position District Exploitation Engineer
Approved OIL CONSERVATION COMMISSION	Send Communications regarding well to:
AA	NameShell Oil Company
Tide	Address Box 1858 Roswell, New Mexico

\*\*\*

11