

NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico



MISCELLANEOUS REPORTS ON WELL

1

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within the days after the Ework specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

	NG OPERATIONS	REPORT ON REPAIRING WELL			
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING			
REPORT ON RESULT OF TEST SHUT-OFF	OF CASING	REPORT ON DEEPE	NING WE	L	
REPORT ON RESULT OF PLUG	GING OF WELL				
<u></u>	Lovington,	New Mexico.	June	8th, 1940.	
OIL CONSERVATION CON Santa Fe, New Mexico. Gentlemen:		Place		Date	
Following is a report on the Magnolia Petroleu	work done and the results ob n Co., State "Control of the second	tained under the h	eading no Well	ted above at th	ne in the
NEL NEL	of Sec. 32	178	R. 341	3	N. M. P. M.,
Vacuum	Field	Lea			County
The dates of this work work	e as follows: 5/31 work was (was not) submitt	./40			
Testi	ED ACCOUNT OF WORK ng 5 ¹ⁿ Casing set at 4 o 1000# Set 1 Hr. Casi	355', Drilled			
Brues W	. Burney	Magnalian	Richard Ant	maine Tr	uaker - Sel
Witnessed by Na	• Burney	Magnalian Company	Delancha		uaker – Sel:
Witnessed by	efore me this	Company I hereby swear above is true Name Position Representing	r or affirm and corre- upt. Magnol	n that the info	Title rmation given

and a second $\mathbf{z} \sim \pi (\mathbf{\hat{3}} \mathbf{x}_{i})_{ij}$

المراجع والمراجع المستعد المراجع المستعد المراجع المراجع

····· •

4.* -

e de la castel de la constante de la constante

 $\mathcal{A}_{\mu\nu}^{\mu\nu}(\mathbf{r},\mathbf{r}) = \mathbf{r}^{\mu\nu} \mathcal{A}_{\mu\nu}^{\mu\nu}(\mathbf{r},\mathbf{r}) + \mathbf{r}^{\mu\nu} \mathcal{A}_{\mu\nu}^{\mu\nu}(\mathbf{r},\mathbf{r}) + \mathbf{r}^{\mu\nu} \mathcal{A}_{\mu\nu}^{\mu\nu}(\mathbf{r}) + \mathbf{r}^{\mu\nu} \mathcal{A}_{\mu\nu}^{\mu\nu}(\mathbf$

· •