

WELL WORK RECOMMENDATIONS
Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: BRIDGE STATE Well No. 7
Field: URQUIM (GREG-S.R.)
County: LEA State: NEW MEXICO

RECOMMENDED PROCEDURE:

1. MOVE IN A PILING UNIT AND PULL THE INJECTION EQUIPMENT.
2. RUN A 5" 12.0 LB/FT, K-55, FLUSH JOINT LINER FROM
APPROXIMATELY 4,165' TO T.D. OF 4,700'. CEMENT WITH
CLASS C MORT CEMENT (14.8 LB/GAL) SLURRY CONTAINING
0.3% CFR-2 (HALLIBURTON'S FRICTION REDUCING AGENT),
CEMENT AT APPROXIMATELY 5 BBL/INCH. APPROXIMATELY
100 SK OF MORT CEMENT WILL BE REQUIRED. USE A
PACK-OFF TYPE LINER-HANGER IN SETTING THE LINER.
3. DRILL OUT PLUGS AND CEMENT TO P.B.T.D. OF 4,645'
AFTER 24 HRS WOG.
4. RUN A GAMMA RAY-COMPENSATED NEUTRON-COLLAR LOG
FROM P.B.T.D. OF 4,645' THROUGH THE MINIMUM LOGGING INTERVAL.
5. SPOT 300 GALS OF 15% NON-EMULSION, TPOIL-STABILIZED
HCL ACID IN THE BOTTOM OF THE HOLE AND PERFORATE
THE SAN ANTONIO FORMATION WITH 1 JET SHOT PTP PLATE HS

8-9-73 JW
Oper. Engr.
Form - 1/73

Page 1 of 2.