

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-1520

7. Lease Name or Unit Agreement Name

BRIDGES STATE

8. Well No.

41

9. Pool name or Wildcat

Vacuum Grayburg San Andres

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Mobil Producing TX & NM, Inc.

3. Address of Operator

P.O. Box 633 Midland, Texas 79702

4. Well Location

Unit Letter P : 660 Feet From The South Line and 660 Feet From The East Line

Section 23 Township 17-S Range 34-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Temporary Abandon ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU Permian Rig #41
POOH/LD rods and pump, NU BOP
POOH w/ 2 3/8 tubing.
RIH w/ Elder CIBP & set CIBP @ 4208
Circ csg. w/ 160 bbls pkr. fluid & test csg to 300# O.K.
Spot 6 sx (35') cap on CIBP

Well TA'd 03-09-90

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE D.W. Parks, Jr.

TITLE Regulatory Technician

DATE 03-12-90

TYPE OR PRINT NAME D.W. Parks, Jr.

TELEPHONE NO. 688-2548

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 14 1990

TA expires 4-1-91

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1520
7. Lease Name or Unit Agreement Name BRIDGES STATE
8. Well No. 41
9. Pool name or Wildcat Vacuum G-SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Mobil Producing TX & NM, Inc.
3. Address of Operator P.O. Box 633 Midland, Texas 79702	4. Well Location Unit Letter P : 660 Feet From The South Line and 660 Feet From The East Line Section 23 Township 17-S Range 34E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU Workover Unit. Unseat pump, POOH w/ rods & pump. Visually check rods for useable stock.
Lay down rods.
NU BOP, test. Release TAC. POOH w/ tbg. & TAC. (If tbg Class B, leave in hole)
Lay down worn tbg.
RIH w/ CIBP, set @ +/- 100' fo open hole section.
Cap CIBP w/ 35' (6 sks). Load casing w/ packer fluid, test to 300 pai.
SI well, attach a 500 psi guage to wellhead to monitor csg. press.

Request authority to temporary abandon well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE D.W. Parks Jr. TITLE Regulatory Technician DATE 02-27-90
TYPE OR PRINT NAME D.W. Parks, Jr. (915) TELEPHONE NO. 688-2548

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAR 01 1990

RECEIVED

FEB 28 1990

DCO
HUMAN OFFICE