

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. NA
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEB <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1520
7. Lease Name or Unit Agreement Name BRIDGES STATE
8. Well No. 19
9. Pool name or Wildcat VACUUM GRAYBURG/SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.) NA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Mobil Producing Tx. & N.M. Inc.*

3. Address of Operator *Mobil Exploration & Producing U.S. Inc., as Agent for
Mobil Producing TX. & N.M. Inc., P. O. Box 633, Midland, TX 79702

4. Well Location
Unit Letter D : 660 Feet From The NORTH Line and 660 Feet From The WEST Line

Section 24 Township 17S Range 34E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
NA

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU MAYO MARRS. ND WH. NU BOP. MI WS.
2. RIH W/CSG & JACKETS - CUT & PULL CSG.
3. SPOT STUB PLUG OF 36 SX CMT 2550-2430.
4. SPOT PLUG OF 47 SX CMT 1750-1633 ACROSS TOP OF 1700 FT. TAG CMT PLUG TOP @ 1633. PU TBG TO 883.
5. SPOT PLUG OF 46 SX CMT 883-772. PU TBG TO 50 FT.
6. SPOT 21 SX FROM 50-SURFACE. POH W/WS. WOC.
7. ND BOP. RD PU. CUST CSG 3 FT BELOW GD LEVEL. WELL PLAT ON CSG STUB. ERRECT P&A MARKER W/WELL NAME AND PLUGGED DATE. FILL CELLAR & CLEAN SURFACE LOCATION.

VERBAL APPROVAL FROM EDDIE SEAY W/NMOCD 6/12/91.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. W. Dixon TITLE Engineering Technician DATE 7/18/91

TYPE OR PRINT NAME J. W. DIXON (915) 688-2452

TELEPHONE NO. 688-2452

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

100

1991

1991