

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-025-02092

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-1520

7. Lease Name or Unit Agreement Name:

Vacuum Glorieta West Unit

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Chevron USA, Inc.

3. Address of Operator
15 Smith Rd. Midland, TX 79705

4. Well Location

Unit Letter L : 1980 feet from the south line and 660 feet from the west line

Section 24 Township 17-S Range 34-E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE
COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND
ABANDONMENT ☒

CASING TEST AND
CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion
or recompilation.

1. RIH Tag 4 1/2 CIBP @ 5822 spot 25sx plug fr/5822-5600(Glorieta)Tag @ 5468
2. Displace hole w/MLF 9.5# Brine w/25# Gel P/BBL.
3. Spot 60sx plug fr/4400-3800(7 shoe, 4 1/2 liner top,Queen)Tag @ 3718
4. Perf 4 holes @ 2600 sqz w/75sx fr/2600-2500(B-salt,Yates)Tag @ 2408
5. Perf 4 holes @ 900 sqz w/75sx fr/900-700(10 3/4 shoe)Tag @ 653
6. Perf 4 holes @ 250 circ cmt 7 X 10 3/4 csg fr/250-surf w/115sx Tag @ surf
7. Install dry hole marker 2-12-03

Approved as to Plugging of the Well Bore.
Liability under bond is retained until
Surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE MANAGER/SUNSET DATE 2-12-03

Type or print name Jimmy BAGLEY
(This space for State use)

Telephone No 915 520-7506

ORIGINAL SIGNED BY

APPROVED BY [Signature] TITLE

Conditions of approval, if any, REPRESENTATIVE II/STAFF MANAGER

DATE

FEB 24 2003