Submit to Appropriate District Office State Lease - 6 copies Fee Lease - 5 copies	Energ				
DISTRICT I P.O. Box 1980, Hobbs, NN		API NO. (assigned by OCD on New Wells) 30-025-02092			
DISTRICT II P.O. Drawer DD, Artesia, I	NM 88210	5. Indicate Type of Lease STATE X PEE			
DISTRICT III 1000 Rio Brazos Rd., Azter	5, NM 87410			6. State Oil & Gas Leas	ie No.
APPLICAT	ION FOR PERMIT	TO DRILL, DEEPEN, C	OR PLUG BACK		
DRILL b. Type of Well: Of Well: WELL X WELL		R DEEPEN X	PLUG BACK	7. Lease Name or Unit Bridges-State	-
2 Name of Operator Mobil Produc	cing Tx. & N.M			8. Well No. 23	
Address of A	ploration & P	9. Pool name or Wildcat Vacuum - Il prieta			
l. Well Location L Unit Letter	1090	From The South	Line and 660		West Line
Section 24	Town	unhip 17S Ram	ge 34E	NMPM Lea	County
		10. Proposed Depth TD-6300		Formation Glorietta	12. Rotary or C.T.
3. Elevations (Show whether	DF, RT, GR, esc.) GR 4016	14. Kind & Status Plug. Bond	15. Drilling Contracto		Date Work will start
<u>4028 K.D</u> 17.	Gr 7016	On File	Unknown		08-92
· · · · · · · · · · · · · · · · · · ·	PF	ROPOSED CASING AN	D CEMENT PROG	RAM	
SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF CEMENT	EST. TOP
<u> 14–1/4</u> 8–3/4	10-3/4	35.5	835	220 sx	Circ.
0-3/4	7	23	4330	220 sx	TOC 2680
	Urigi	nal Casing Undist	urbed		
6-1/4	4-1/2 Liner	10.5	TOL 3900	425 Sx C1	C

Well currently in San Andres field. Drill deeper request to Glorietta Formation. Procedure and proposed wellbore sketch attached.

V	tion above is true and complete to the best of	my knowledge and belief	
skonature	HULLOCK	- mu Engineering	Technician 10-30-92 Texas & New Mexico Inc.
TYPE OR PRINT NAME Kay	ye Pollock	ACTION by and th	hrough its agent An & Producing U.S. Thermone NO. (915) 688
(This space for State Use)	Orig. Signed by Paul Kautz		
AFFROVED BY	Geologist	TITLE	NOV () *:>
CONDITIONS OF AFTROVAL, IF A	NY:		

Submit to Appropriate District Office State Lease - 4 copies Fee Lease - 3 copies

DISTRICT | P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM \$8210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL LOCATION AND ACREAGE DEDICATION PLAT

		All Dis	tances must b		er boundarie	es of the section		
Operator				Lease				Well No.
	CING TX & NM		MIDLAND T		STATE			23
Unit Letter	Section	Township		Range			County	
L	24	17	<u>'S</u>		34E	NMP	1	LEA
Actual Footage Loc	ation of Well:							
1980 Fround level Elev.	feet from the	SOUTH	line and		660	feet from	the WES	tme
	Produc	ing Formation		Pool		a)		Dedicated Acreage: 40
4028		GLORIETTA		VACUUM	All is ?	uita		SSE1.28 Acres
2. If mor 3. If mor	e the screage dedicat e than one lease is do e than one lease of d	edicated to the well, ifferent ownership is	outline each an	d identify the o	wnenhip ther	reof (both as to work	-	
	tion, force-pooling, e Yes]No Ifan	swer is "yes" ty					
	is "no" list the owne	ers and tract descript	ions which have	e actually been	consolidated.	(Use reverse side o	r	
	if neccessary.	to the well wetil all	internete have b		4.6			
or until a	able will be assigned non-standard unit, el	i to the well that all liminating such inter	est, has been ap	proved by the I	o (by commu Division.	muzzuon, unitizzbo	n, forced-poolin	g, or otherwise)
							OPERAT	OR CERTIFICATION
	!	17S	34E		1			certify that the information
					1		ontained herei	n in true and complete to the lodge and belief.
					1		ignature/	Pollock
					1		Tinted Name	
			† 		†		KAYE POLL	DCK
	1				1	1 -		Y TECHNICIAN
	i						Company MORII F&P	US AS AGENT-MPTM
	ł					-4 (Date	10-30-92
	i		24				SURVEY	OR CERTIFICATION
L	·				<u>∤</u> 1			that the well location show
660' 2	23						n this plat we ctual surveys upervison, and	s plotted from field notes of made by me or under my ! that the same is true and
1						4	orrect to the whief.	best of my knowledge and
ا جہ جہ جہ جہ					 		Date Surveyed	
1980'					 		Signature & Sea Professional Sur	
۱ 	 				 		Certificate No.	
330 660	990 1320 1650	1980 2310 264	10 200	0 1500	1000	500 0		

DRILL DEEPER AND SURVEY PROCEDURE

— .

MIRU pulling unit with pumps, mud system, and power swivel. ND WH and NU BOP.

TIH with a 6-1/4" mill tooth journal-bearing bit on (15) 4-3/4" (54 lb/ft) DC, and 2-7/8", 10.4#, grade E, AOH DP to 4,150'. Shut-in backside and pressure test 7" casing to 1500# for 30 minutes. If casing holds pressure, go to step #5.

POH with 2-7/8" DP, 4-3/4" DC and 6-1/4" bit. PU a packer for 7" 24# casing. T1H to 4.150' & set packer. Test C1BP to 1500#. If C1BP holds, PUH 500' and test casing to 1500# for 30 minutes. Continue testing up the hole until the casing leak is isolated. Establish an injection rate and pressure for the leak. Contact E. L. Cash @ (915) 688-1404 for a squeeze procedure.

WOC 24 hrs. TIH with a 6-1/4" mill tooth bit w/ (15) 4-3/4" DC, and 2-7/8" DP. DO all cement plugs. Shut-in backside and test casing to 1500# for 30 minutes.

Drill out CIBP at 4,230' w/ 35' cement cap (PBTD @ 4,195') and a CIBP at 4,245' (This CIBP would not set and was left in the hole. The setting depth is not definite.) Clean out hole to TD @ 4,700'. Drill 10' of new formation.

POH with 6-1/4" bit, DC, and DP. TIH w/ 6-1/4" Smith F-4 insert bit w/ (15) 4-3/4" DC, and 2-7/8" DP.

Drill to TD @ 6,300'. Run TOTCO surveys every 500' while drilling new formation.

CEMENTING PROCEDURE

Two pump trucks with recirculating type mixers will be required. One pump truck will be used as a standby only. Use a pressurized mud balance to check the cement density. Record the following job parameters versus time: pump rate, pump pressures, fluid density and total volumes pumped. Collect cement samples per procedure in appendix.

Reciprocate the liner 10' - 15' (2-3 minutes per stroke). Reciprocate while conditioning the hole, mixing cement and displacing cement. If surge and swab pressures are excessive, discontinue reciprocation. Circulate at least one hole volume prior to cementing.

Pressure test lines to 3000 psi for 5 minutes, prior to cementing.

Preceed cement with 25 bbls of fresh water.

Pump cement downhole at 4 bpm.

Displace cement with 55 bbls of fresh water. DO NOT OVER-DISPLACE.

1

Release liner. POOH with running tool and lay down drillpipe.

WOC 24 hrs. TIH w/ 7" packer. Test TOL to 500# for 30 minutes. If TOL holds, turn well over to production. If TOL leaks, contact E. L. Cash @ (915) 688-1404 for a liner top squeeze procedure.









Υ.