

NO. OF COPIES RECEIVED

DISTRIBUTION

SANTA FE

FILE

U.S.G.S.

LAND OFFICE

OPERATOR

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease

State ☒

Fee ☐

5. State Oil & Gas Lease No.

B-1520

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ONLY USE FOR SUCH PROPOSALS.)

SUNDRY NOTICES AND REPORTS ON WELLS

DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ONLY USE FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTH ☐

2. Name of Operator

Mobil Oil Corporation

3. Address of Operator

Box 633, Midland, Texas 79701

4. Location of Well

UNIT LETTER F 1980 FEET FROM THE North LINE AND 1978.5 FEET FROM

THE West LINE, SECTION 25 TOWNSHIP 17 S. RANGE 34-E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

Bridges State

9. Well No.

11

10. Field and Pool, or Wildcat

Vac. Blinbry

15. Elevation (Show whether DF, RT, GR, etc.)

4013 GR

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENT ON TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☒

CHANGE PLANS ☐

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Cement plug to be spotted across and above perfs, 6412-6563, 40 sx for plug from 6300-657'. Circulate hole with brine water and load hole. Determine free point on 7" 24# casing. If 1600' or above check step 7. Cut and pull available 7" pot 100' cement plug across 7" cut stub, 45 sx for plug and -- Spot 100' cement plug in 9" open hole above stub w/50 sx Or---inside 7" casing below stub w/25 sx AT 1650'-1750' for cover salt top at 1700' circulate hole to mud laden fluid - 25 sx salt gel per 100 bbls. Spot 100' cement plug across 1-3/4" casing shoe at 750'-55 sx. Spot 10 sx cement plug at surface. Erect monument and clear location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE Authorized Agent

DATE 11-27-74

APPROVED

TITLE

DATE