

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease State ☒ For ☐
5. State Oil & Gas Lease No. B-2706

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG SAG TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER- ☐	7. Unit Agreement Name Central Vacuum Unit
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name Central Vacuum Unit
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 23
4. Location of well: UNIT LETTER K 1980 South 1980 FEET FROM THE LINE AND FEET FROM West 25 17-S 34-E THE LINE, SECTION TOWNSHIP RANGE NMPM.	10. Field and Pool, or Wildcat Vacuum Unit
15. Elevation (Show whether LF, RT, GR, etc.) 4013' (DF)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
OTHER ☐		OTHER <u>Addl. Perfs In San Andres</u> ☒	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RIGGED UP. PULL RODS AND PUMP. INSTALL BOP. PULL TUBING.
2. PERFORATE 4 1/2" CASING W/2-JSPF @ 4396', 4401', 04', 11', 17', 26', 34', 38', 41', 44', 4582', 90', 90', 4607', 52', 68', 72', 98', & 4701'.
3. SET PKR @ 4498'. ACIDIZE PERFS 4668'-4736' W/3000 GALS 20% NEFE HCL ACID IN 3-STAGES USING 800# MOTH BALLS, 800# ROCK SALT AND 1 DRUM WAYPLEX 55-S SCALE INHIBITOR BETWEEN STAGES.
4. RESET PKR @ 4313'. ACIDIZE PERFS 4396'-4444' W/3000 GALS 20% NEFE HCL ACID IN 3 STAGES USING 700# MOTH BALLS, 700# ROCK SALT AND 1 DRUM WAYPLEX 55-S SCALE INHIBITOR BETWEEN STAGES.
5. INSTALL PUMPING EQUIPMENT. TEST AND RETURN TO PRODUCTION.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst Dist Mgr DATE 3-21-84

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAR 23 1984
CONDITIONS OF APPROVAL, IF ANY: