

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No. B-1520	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER- ☐		7. Unit Agreement Name
2. Name of Operator Mobil Oil Corporation		8. Farm or Lease Name Bridges State
3. Address of Operator P.O. Box 633, Midland, Texas		9. Well No. 25
4. Location of Well UNIT LETTER <u>S</u> 1980 FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>26</u> TOWNSHIP <u>17-S</u> RANGE <u>34-E</u> NMPM.		10. Field and Pool, or Wildcat Vacuum Grayburg S.A.
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER <u>C.O. & Convert to W.I.W.</u> ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Clean Out to PBTD & Convert to Water Injecting Well as per attached Procedures.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Authorized Agent DATE 11-11-69

APPROVED BY [Signature] TITLE DATE 11-11-69

CONDITIONS OF APPROVAL, IF ANY:

MIDLAND E & P DIVIS

WELL WORK RECOMMENDATIONS

Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: BRIDGES STATE Well No. 25

Field: VACUUM (GRAYBURG-SAN ANDRES)

County: LEA State: N. MEXICO

RECOMMENDED PROCEDURE:

1. MIRU PULLING UNIT. PULL RODS, PUMP AND TUB.
2. CLEAN OUT TO 4579 FT (P.B.T.D).
3. RUN TUBING AND TREATING PACKER TO 4150'.
4. ACIDIZE OPEN HOLE 4200'-4579' WITH 5,000 GALS
N.E., IRON STABILIZED, HCL FOLLOWED BY 15,000 GALS
FRESH WATER TREATED WITH 2 GALS. ADOMALL PER 1000
GALS WATER. TREAT AT .5 TO 1.0 BPM. INJECT 1400 LBS. ROCK
SALT - 350 LBS. AFTER EACH 1000 GALS ACID FOR SELECTIVITY.
EACH STAGE OF ROCK SALT SHOULD BE CARRIED IN A
SOLUTION OF SATURATED SALT WATER.
5. PULL TUBING AND PACKER.
6. PICK UP 4150 FT. CEMENT LINED TUBING WITH
INJECTION TYPE PACKER.
7. WITH PACKER AT 4150 FT. CIRCULATE COROTRON 2207
CORROSION INHIBITOR IN ANNULUS. (1% SOLUTION).
8. SET PACKER AND HOOK UP WELL HEAD FOR INJECTION.

Rem 4/10/69

Bridges State Well No. 2.5

Vacuum (Greeburg-San Andres) Field

Lea County, New Mexico

