

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
B-8097-A

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|---|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Water Injection</u> | 7. Unit Agreement Name <u>West Vacuum Unit</u> |
| 2. Name of Operator <u>Texaco, Inc.</u> | 8. Farm or Lease Name <u>West Vacuum Unit</u> |
| 3. Address of Operator <u>P.O. Box 728, Hobbs, New Mexico 88240</u> | 9. Well No. <u>14</u> |
| 4. Location of Well UNIT LETTER <u>E</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>33</u> TOWNSHIP <u>17-S</u> RANGE <u>34-E</u> HMPM. | 10. Field and Pool, or Wildcat <u>Vacuum Grayburg</u> <u>San Andres</u> |
| 15. Elevation (Show whether DF, RT, GR, etc.) <u>4068' (DF)</u> | 12. County <u>Lea</u> |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|---|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input checked="" type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> | |
| | | OTHER <u>Clean Out & Run Production Survey</u> <input checked="" type="checkbox"/> | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Pull rods, pump and tubing.
2. Clean out to 4706'.
3. Install pumping equipment. Ran production Survey.
4. Test well and return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Asst. Dist. Mgr. DATE 2-26-82

ORIGINAL SIGNED BY
JERRY SEXTON

APPROVED BY DISTRICT MGR. TITLE MAP DATE 1982

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 20 1982

O.C. L.
HOBBS OFFICE