Submit 3 copies State of New Mexico Form C-103 gy, Minerals and Natural Resources Department to Appropriate District Office Revised 1-1-89 DISTRICT I OIL CONSERVATION DIVISION WELL API NO. P.O. Box 1980, Hobbs, NM 88240 3002502186 P.O. Box 2088 DISTRICT II 5. Indicate Type of Lease Santa Fe, New Mexico 87504-2088 P.O. Box Drawer DD, Artesia, NM 88210 STATE V DISTRICT III 6. State Oil / Gas Lease No 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI WEST VACUUM UNIT (FORM C-101) FOR SUCH PROPOSALS. 1. Type of Well: GAS WELL WELL OTHER 8. Well No. 2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC. 9. Pool Name or Wildcat 3. Address of Operator PO BOX 3109, MIDLAND, TX 79702 VACUUM GRAYBURG SAN ANDRES 4. Well Location Unit Letter H: 1980 Feet From The NORTH Line and 660 Feet From The EAST Township 17S Range 34E 10. Elevation (Show whether DF, RKB, RT,GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PERFORM REMEDIAL WORK PLUG AND ABANDONMENT CHANGE PLANS COMMENCE DRILLING OPERATION TEMPORARILY ABANDON PULL OR ALTER CASING CASING TEST AND CEMENT JOB REQUEST TA STATUS OTHER 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 8-14-01: NOTIFY NMOCD. SET CIBP @ 4025'. TEST CSG TO 540# - 30 MINS. CHART ATTACHED. PERFS: 4110-4685'

WELL IS TEMPORARILY ABANDONED.

This Approval of Temporary Abandonment Expires I hereby certify that the **Engineering Assistant SIGNATURE** DATE 8/29/01 Telephone No. 915-688-4752 TYPE OR PRINT NAME J. Denise Leake (This space for State Use) **APPROVED** BUNDITIONS OF APPROVAL IF ANY

