DISTRICT III

P.O. Box 1980, Hobbs, NM 88240

P.O. Drawer DD, Artesia, NM 88210

1000 Rio Brazos Rd., Aztec, NM 87410

## State of New Mexico Et. Jy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

Santa Fe, NM 87505

2040 Pacheco St.

Form C-103 Revised 1-1-89

FEE

Line

STATE X

WELL API NO

3002502188

sIndicate Type of Lease

State Oil & Gas Lease No

B-1576 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" West Vacuum Unit (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: OIL WELL injection WELL OTHER ₅Well No. 2Name of Operator Texaco E&P Inc 3Address of Operator Pool name or Wildcat P.O.Box 3109, Midland, Texas 79702 Vacuum Grayburg San Andres √Well Location 990 North Unit Letter Feet From The 990 East Line and Feet From The 33 Section 17S 34E Township Range Lea **NMPM** County 10 Elevation (Show whether DF, RKB, RT, GR, etc.) 4062 GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ANBANDONMENT PULL OR ALTER CASING **CASING TEST AND CEMENT JOB** OTHER: OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103 1.Notifey N.M.O.C.D. 24 hours prior starting plugging
2.MIRU pulling unit NUBOP
3.RIH tag CIBP @4180 circlate hole w/ 9.8 mud spot 25sx. cement on top
4.spot 25sx. cement from 3870 to3770 (Queen)
5.perf. 4 holes @2820 squ. 50 sx. cement (yates)
6.perf. 4 holes @2750 squ. 50 sx. cement (B. salt)
7.70cf. 4 holes @1870 squ. 50 sx. cement (T. salt) THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE & CONTINUE OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED. 7.perf. 4 holes @1670 squ. 50 sx. cement (T. salt )
8. perf. 4 holes @1400 squ. 60 sx. cement (T. anhy )
9.perf. 4 holes @60 ft. circlate cement in &out of 7" casing 10.R.D.M.O., cut off well head, install dry hole marker, clean location

I hereby certify that the information above is true and complete to the best of my knowledge and belief SIGNATURE TITLE Reservoir Engineer DATE 06-09-98 TYPE OR PRINT NAME Dave Deax TELEPHONE NO 915-688-4492

(This space for State Use)

APPROVED BY

Orig. Signed by Paul Kautz Geolog in

TITLE

CONDITIONS OF APPROVAL, IF ANY

Received Hobbs Octo