

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-79

NO. OF	RECEIVED	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
State ☒ For ☐
5. State Oil & Gas Le No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name West Vacuum Unit
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name West Vacuum Unit
3. Address of Operator P. O. Box 728, Hobbs, New Mexico, 88240	9. Well No. 37
4. Location of Well UNIT LETTER P 4620 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 34 TOWNSHIP 17-S RANGE 34-E NMPM.	10. Field and Pool, or Wildcat Vacuum Grayburg-San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4036' (GR)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

REMARKS

1. WELL STATUS - Shut-in.
2. TEMPORARY ABANDONMENT DATE - November 16, 1980
3. REASON FOR ABANDONMENT - Uneconomical to produce, stuck pump.
4. FUTURE PLANS - Held for remedial work.
5. DATE OF FUTURE WORKOVER OR PLUGGING - 1st Quarter, 1981.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE ASST. DIST. SUPT. DATE 1/13/81
APPROVED BY Jerry Brown TITLE Dist. L. Supv. DATE 1/16/82