

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

|                                                                                                      |
|------------------------------------------------------------------------------------------------------|
| 5a. Indicate Type of Lease<br>State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No.<br>B-871                                                                |
| 7. Unit Agreement Name<br>West Vacuum Unit                                                           |
| 8. Farm or Lease Name<br>West Vacuum Unit                                                            |
| 9. Well No.<br>35                                                                                    |
| 10. Field and Pool, or Wildcat<br>Vacuum Grayburg San Andre                                          |
| 12. County<br>Lea                                                                                    |

**SUNDRY NOTICES AND REPORTS ON WELLS**  
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator  
TEXACO Inc.

3. Address of Operator  
P. O. Box 728 - Hobbs, New Mexico 88240

4. Location of Well  
UNIT LETTER N 1980 FEET FROM THE West LINE AND 660 FEET FROM  
South LINE, SECTION 34 TOWNSHIP 17-S RANGE 34-E NMPM.

13. Elevation (Show whether DF, RT, GR, etc.)  
4041' (DF)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

| NOTICE OF INTENTION TO:                        | SUBSEQUENT REPORT OF:                               |
|------------------------------------------------|-----------------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input checked="" type="checkbox"/>   |
| TEMPORARILY ABANDON <input type="checkbox"/>   | COMMENCE DRILLING OPNS. <input type="checkbox"/>    |
| PULL OR ALTER CASING <input type="checkbox"/>  | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| OTHER <input type="checkbox"/>                 | OTHER <input type="checkbox"/>                      |
| PLUG AND ABANDON <input type="checkbox"/>      | ALTERING CASING <input type="checkbox"/>            |
| CHANGE PLANS <input type="checkbox"/>          | PLUG AND ABANDONMENT <input type="checkbox"/>       |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Pull rods and pump.
2. Spot 250 gals Xylene, 750 gals 15% NE Acid and 165 gals Sulfate Converter over open hole section 4170-4700'.
3. Set pkr. @ 4050'. Acidize open hole 4170-4700' w/4500 gals 15% gel acid in 3 equal stages using 600# rock salt between stages.
4. Install production equipment. Test and return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. District Supt. DATE 9-20-77

APPROVED BY [Signature] TITLE [Signature] DATE SEP 22 1977

CONDITIONS OF APPROVAL, IF ANY: