NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELL

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

OPERATIONS	DRILLING	i.	REPORT ON REP.	AIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL REPORT ON RESULT OF TEST OF CASING SHUT-OFF		· · ·	REPORT ON PULLING OR OTHERWISE ALTERING CASING		
			REPORT ON DEE		
REPORT ON RESULT OF	PLUGGING OF WEL	T -			
			Odessa, Texas	May	6, 1939
OIL CONSERVATION COM	IMISSION,		Place		Date
Santa Fe, New Mexico.					a in a sector
Gentlemen:				Ange -	
Following is a report on the Phillips Fetrole	um Jompany		Hale		ve at the in the
•	any or Operator	nc	Lease		4 10
• •					4-E , N. M. P. M.,
					County
The dates of this work wer		•			
Notice of intention to do th and approval of the propos	ie work was (wese) ed plan was (weso)	tt submitt	ed on Form C-102 on l. (Cross out incorrec	et words)	
DETAILE	D ACCOUNT OF	F WORK	DONE AND RES	SULTS OBTA	INED
T.D. 4198 Lime.	Tested water	shut-of:	f on 7" casing	with 1000#	
	Tested water pressure bef	shut-of: ore and a	f on 7" casing after drilling	with 1000#	
	Tested water	shut-of: ore and a	f on 7" casing after drilling	with 1000#	
	Tested water pressure bef	shut-of: ore and a	f on 7" casing after drilling	with 1000#	
	Tested water pressure bef	shut-of: ore and a	f on 7" casing after drilling	with 1000#	
	Tested water pressure bef	shut-of: ore and a	f on 7" casing after drilling	with 1000#	
T.D. 4198 Lime.	Tested water pressure bef	shut-of ore and a isfactor	f on 7" casing after drilling	with 1000# cement plug	HOLES OFFICE
T.D. 4198 Lime.	Tested water pressure before Shut-off sat: L. Smith Name	shut-of ore and isfactor Phi	f on 7" casing after drilling y llips Petroleum Company I hepeny swear or 2	with 1000# cement plug	HOLES OFFICE
T.D. 4198 Lime. Witnessed by Subscribed and sworn to be	Tested water pressure before Shut-off sat: L. Smith Name	shut-of ore and isfactor Phi	f on 7" casing after drilling y llips Petroleum _{Company}	with 1000# cement plug	HOLFS OFFICE
T.D. 4198 Lime. Witnessed by	Tested water pressure before Shut-off sat: L. Smith Name	shut-of ore and isfactor Phi	f on 7" casing after drilling y llips Petroleum Company I hepeny swear or 2	with 1000# cement plug	HOLFS OFFICE
T.D. 4198 Lime. Witnessed by Subscribed and sworn to be 	Tested water pressure before Shut-off sat: L. Smith Name Pefore me this May	shut-of ore and isfactor Phi 	f on 7" casing after orilling y llips Petroleum Company I hepety syear or a is the are correct. Name	with 1000# cement plug Co. L offirm that the i	HOLES OFFICE case Foreman Title information given above
T.D. 4198 Lime. Witnessed by Subscribed and sworn to be	Tested water pressure before Shut-off sat: L. Smith Name Pefore me this May	shut-of ore and isfector Phi 	f on 7" casing after orilling y llips Petroleum Company I hepetry swear or a is the are correct. Name Position Distri	with 1000# cement plug Go. L offirm that the i	HOISES OFFICE ease Foreman Title information given above
T.D. 4198 Lime. Witnessed by Subscribed and sworn to be 6th day of	Tested water pressure before Shut-off sat: L. Smith Name Pefore me this May	shut-of ore and isfector Phi 	f on 7" casing after orilling y llips Petroleum Company I hepetry swear or a is the are correct. Name Position Distri	with 1000# cement plug Go. L affirm that the i C. Superint ct Superint 11ips Petro	HOLES OFFICE case Foreman Title information given above
T.D. 4198 Lime. Witnessed by Subscribed and sworn to be 6th day of	Tested water pressure before Shut-off sat: L. Smith Name efore me this May Notary Pu	shut-of ore and isfector Phi 	f on 7" casing after orilling y llips Petroleum Company I hepety syear or a is the are correct. Name Position Distri Representing Phi	with 1000# cement plug Co. L offirm that the in Co. Co. L offirm that the in Co. Co. Co. Co. Co. Co. Co. Co. Co. Co.	HOISES OFFICE

•

Ľ,

ر