

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	3002502226
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	857948
7. Lease Name or Unit Agreement Name	VACUUM GRAYBURG SAN ANDRES UT
8. Well No.	66
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter L : 1980 Feet From The SOUTH Line and 660 Feet From The WEST Line
Section 35 Township 17S Range 34E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ ACIDIZE & SCALE SQUEEZE

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-13-99: MIRU. UNSEAT PUMP. NDWH. NUBOP. REL TAC. TIH W/BIT & BAILER TO 960'.
9-14-99: TIH W/TBG. TAG FILL @ 4679'. C/O 4690-11'. TIH W/PKR ON TBG & TEST TO 5000#. PSA 4135'. RU KILL TRUCK & LOAD & TEST CDG TO 5000#.
9-15-99: PRESS BACKSIDE TO 500#. ACIDIZE PERFS 4192-4690' W/7000 GALS 15% NEFE HCL & 3000# RK SLT.
9-16-99: RU SWAB. TIH TO SN @ 4135'-NO FLUID. RD SWAB. RU PUMP TRUCK & SCALE SQZ O.H. 4192-4690' W/110 GALS TH-756 MIXED IN 20 BFW. FLSH W/200 BFW. REL PKR. TIH W/TBG. TAG SALT FILL @ 4655'. PULL UP TO 4130'.
9-17-99: TIH TO 4655'. RU PUMP TRUCK. C/O SALT FILL TO 4690'. RD PMP TRUCK. TIH W/OPSMA, PERF SUB, SN, TBG, & TAC. NDBOP. & SET TAC. NUWH. MA @ 4687'. SN @ 4657'. TAC @ 4104'. TIH W/GAS ANCHOR, PUMP, SNKR BARS, RDS. HUNG ON & TEST TO 500#-OK.START PUMPING UNIT. PUMP STUCK ON UPSTROKE.
9-18-99: C/O PUMP. TIH W/PMP & RDS. HUNG ON. PUMPING @ 10:00 AM.
9-20-99: RIG DOWN.
10-06-99: ON 24 HR OPT. PUMPING 16 BO, 6 BW, & 7 MCF. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 11/04/1999
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: