

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.  
Unavailable

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
TEXACO, Inc.

3. Address of Operator  
P. O. Box 728, Hobbs, New Mexico 88240

4. Location of Well  
UNIT LETTER K 1840 FEET FROM THE West LINE AND 2140 FEET FROM  
THE South LINE, SECTION 36 TOWNSHIP 17-S RANGE 34-E N.M.P.M.

7. Unit Agreement Name  
Central Vacuum Unit

8. Farm or Lease Name  
Central Vacuum Unit

9. Well No.  
79

10. Field and Pool, or Wildcat  
Vacuum Grayburg  
San Andres

15. Elevation (Show whether DF, RT, GR, etc.)  
Unavailable

12. County  
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Deepened in San Andres</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Installed BOP. Pull tbg. and submersible pump.
2. Drilled new hole to 4710' (new TD). Spotted with 500 gal. acid.
3. Logged well.
4. Acidized open hole 4252-4710' with 15,000 gal. acid in 4 stages 2200# moth balls and 2200# RS between stages.
5. Installed production equipment. Test and return to production.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. B. L. L. TITLE District Operations Manager DATE March 22, 1985

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT 1 SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE MAR 28 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 27 1985

OFFICE  
HOLMES OFFICE