

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. B-1565
7. Unit Agreement Name Central Vacuum Unit
8. Farm or Lease Name Central Vacuum Unit
9. Well No. 52
10. Field and Pool, or Wildcat Vacuum Grayburg San Andres Unit
11. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
FOR APPLICATION FOR PERMIT TO FORM C-103 FOR SUCH PROPOSALS.)

OIL WELL ☒	GAS WELL ☐	OTHER ☐
Name of Operator TEXACO Inc.		
Address of Operator P.O. Box 728 Hobbs, New Mexico 88240		
Location of Well UNIT LETTER B 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 17-S RANGE 34-E N.M.		
12. Elevation (Show whether DF, RT, GR, etc.) Unknown		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	☐
TEMPORARILY ABANDON	☐
PULL OR ALTER CASING	☐
OTHER	☐

PLUG AND ABANDON	☐
CHANGE PLANS	☐
OTHER	☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK	☐
COMMENCE DRILLING OPNS.	☐
CASING TEST AND CEMENT JOB	☐
OTHER Deepen & Treat in San Andres	☒

Continued on back of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

1. Rig Up. Pull pump, rods and tubing.
2. Clean out to TD-4650' and deepentto 4730'. Log Well.
3. Set pkr @ 4556'. Acidize open-hole 4556'-4730' w/1000 gal 15% NE Acid in 2-equal stages using 500# rock salt & 500# Benzoic Acid Flakes between stages.
4. Frac open-hole 4556'-4730' w/15,000 gal gelled water & 19,250# 20/40 sand.
5. Set pkr @ 4073' Acidize open-hole 4098'-4454' w/2000 gal 15% NE Acid containing 50% xylene and 18,500# 20/40 sand in 2-equal stages using 750# salt and 250# Benzoic Acid Flakes between stages.
6. Frac w/28,000 gal gelled water in 2-equal stages using 1000# salt & 750# Benzoic Acid Flakes between stages.
7. Install pumping equipment. Test and place on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *H L Cooper* TITLE Asst. Dist. Supt. DATE 10-27-78
 APPROVED BY Jerry Sexton TITLE Dist. 1, Supv. DATE OCT 30 1978
 CONDITIONS OF APPROVAL, IF ANY: