## Submit 3 copies to Appropriate

(This space for State Use)

APPROVED BY\_

CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico En/ \_\_\_ Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office				
DISTRICT I	OIL CONSERV	ATION DIVISION	WELL API NO.	
P.O. Box 1980, Hobbs, NM 88240	P.O. Bo		30-025-02234	
DISTRICT II		Mexico 87504-2088	5. Indicate Type of Lease	
P.O. Box Drawer DD, Artesia, NM 882	10 Sama re, New I	VIEVIOO 01204-5000		E 🔲
DISTRICT III			6. State Oil / Gas Lease No.	
1000 Rio Brazos Rd., Aztec, NM 8741			B-2146	
SUNDRY NO	TICES AND REPORTS O	N WELL		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name	
UIFFERENT RESE (FORM	C-101) FOR SUCH PROPOSA	ALS.)	CENTRAL VACUUM UNIT	
OII — GAS			1	
1. Type of Well: WELL WELL				
2. Name of Operator			8. Well No. 80	
TEXACO EX	PLORATION & PRODUCTIO	N INC.		
3. Address of Operator P.O. BOX 730, HOBBS, NM 88240			9. Pool Name or Wildcat	
			VACUUM GRAYBURG SAN ANDRES	
4. Well Location	4000 Fact From The	SOUTH Line and 660	Feet From The WESTLine	
Unit Letter			<del></del>	
Section 36	_ Township 17S	Range <u>34E</u> N	MPM LEA_ COUNTY	
	•	er DF, RKB, RT,GR, etc.) 4001' DF		
	TO. Elevation (Show whether	4001 DF		
11. Check A	ppropriate Box to Indica	ate Nature of Notice, Repor	t, or Other Data	
			JBSEQUENT REPORT OF:	
NOTICE OF INTENTION			 F-1	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	님
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP	ERATION PLUG AND ABANDONMENT	Ш
PULL OR ALTER CASING		CASING TEST AND CEME	NT JOB	
OTHER:		OTHER:		
12. Describe Proposed or Completed C	Operations (Clearly state all p	ertinent details, and give pertine	nt dates, including estimated date of starti	ng
any proposed work) SEE RULE 110				
8/19/94 - 8/30/94				
2.12.12			A ODOGE DEBTE AND SION	
1. MIRU, TOH W/ TBG & SUBPUMP.	C/O TO 4655'. SPTD 300 GA	LS AMMONIUM BICARBONATE	ACROSS PERFS AND SION.	
2. SWABBED BACK AMMONIUM BICA	ARBONATE. SPTD 300 GAL	S 15% HCL NEFE ACROSS PERF	S & SI 1 HR. SWABBED BACK ACID.	
3. TIH W/ TREATING PKR. AND SET		IZED PERFS FROM 4009'-4300' V	V/ 8,000 GALS 15% NEFE HCL.	
MAX $P = 3500$ #, AIR = 4 BPM. SION	1. SWABBED BACK.			
4. SCALE SQZD W/ 6 DRUMS TH-793	IN 50 BFW. OVERFLUSHED	W/ 500 BFW. SION.		
5. TOH W/ PKR. TIH W/ TBG & SUB	PUMP. RETURNED WELL T	O PRODUCTION.		
OPT 9-9-94 PUMPING BY SUBPUM	D. OE BODD 2800 BW/PD 60	MCFD		
OPT 9-9-94 POMPING BT SOBPOM	F. 90 BOT D, 2003 BVV B, 00	, 11101 15		
I hereby certify that the information above is true and car	nplete to the best of my knowledge and belie	ıf.		
SIGNATURE From Col	m TITLE	Cara Assi	DATE 11/1/94	
			Talaghana Na 207 0440	
TYPE OR PRINT NAME	Monte C. Duncan		Telephone No. 397-0418	

\_TITLE\_

DATE\_