

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-02238
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	857943
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	77
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>I</u> : <u>1980</u> Feet From The <u>SOUTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>36</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ UNDERREAM, LOG, ACIDIZE

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-28-00: MIRU. NDWH. NUBOP. TIH W/BIT, DC'S. PU TBG TO 1089'.
2-29-00: WASH 4684-4710'. DRILL NEW FORMATION 4710-4730'.
3-01-00: TIH TO 4720'. DRILL FORM 4730-4760'. TIH W/UNDERREAMER #1, DC'S, & TBG TO 3986'.
3-02-00: TIH TO 4121'. REAM 4121-4123'. REAMER STUCK. START REAM 4123-4135'.
3-03-00: TIH W/REAMER #2, DC'S & TBG TO 4121'. ESTAB CIRC W/200 BBLS. REAM 4121-24'. TIH W/REAMER #3, DC'S & TBG TO 4070'.
3-06-00: KILL W/CUT BRINE. TIH TO 4150'. REAM 4150-4196.
3-07-00: TIH TO 4196'. REAM 4196-4216'.
3-08-00: TIH W/REAMER #4, DC'S & TBG TO 4216'. REAM 4216-4219. TIH W/REAMER #5.
3-09-00: TIH TO 4125'. TIH TO 4130'. REAM 4340-4438'.
3-10-00: TIH W/REAMER #6, DC'S & TBG T TO 4438'. UNDERREAM 4438-4470'. TIH W/REAMER #7 TO 4040'.
3-13-00: TIH TO 4470'. UNDERREAM 4470-4528'.
3-14-00: REAM 4528-4532'. TIH W/REAMER #8 TO 4532'. REAM 4532-4686'.
3-15-00: TIH W/REAMER #9 TO 4680. REAM TO 4758'. JUNK IN FORM WALL @ 4125,4216, 4219'.
3-17-00: TIH W/BIT, DC'S & TBG. TAG @ 4755'. WASH 4755-60.
3-20-00: INSTL LUBRICAYOR. RAN GUAGE RING FR SURF TO 4757'. TIH W/LOG TOOL. RAN GR/CNL 4757-2400. TIH W/PKR, SN, & TBG TO 4016'. SET PKR.
3-21-00: ACIDIZE O.H. 4099-4760 W/8000 GALS 15% NEFE HCL ACID.
3-22-00: PUMP CHEM SQZ-10 BBLS FR W/20 GALS ALPHA 133, 10 BFW SPACER, 65 BFW & FLISH W/500 BFW. NDBOP. NU WH. NUBOP. TEST TO 300 PSI.
3-23-00: REL PKR. TIH W/BIT, DC'S & TBG TO 4760'. TIH W/PROD TBG TO 4050.
3-24-00: TIH W/SUB PUMP EQPT. NDBOP. NUWH. PUMP UP @ 4:30 PM.
3-31-00: ON 24 HR OPT. PUMPED 158 BO, 1144 BW, & 507 MCF. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 4/11/00

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY: TITLE

DATE