NO. OF COPIES RECEIVED]		
DISTRIBUTION			Form C-103
SANTAFE			Supersedes Old C-102 and C-103
FILE	NEW MEXICO OIL CON	SERVATION COMMISSION	Effective 1-1-65
U.S.G.S.			
LAND OFFICE			Sa. Indicate Type of Lease
			State X Fee
OPERATOR			5. State Oil & Gas Lease No.
			B-155
SUN	IDRY NOTICES AND REPORTS ON	JWELLS	Ammininin .
USE "APPLI	IDRY NOTICES AND REPORTS ON PROPOSALS TO DRILL OR TO DEEPEN OR PLUG ICATION FOR PERMIT - " (FORM C-101) FOR SU	BACK TO A DIFFERENT RESERVOIR.	- VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
			7. Unit Agreement Name
WELL WELL	OTHER.		1. Out Addement Ndme
2. Name of Operator	8. Farm or Lease Name		
TEXACO Inc.			
3. Address of Operator			New Mexico 'O' St. NCT-
P.O. Box 728, Hobbs	9. Well No.		
4. Location of Well	A HOM HOMELEO BOZ +0		10
0	1980 Frank		10. Field and Pool, or Wildcat San
ONTI CETTER,,	1980 FEET FROM THE East	LINE AND 600 FEET FRO	Vacuum Grayburg Andre
South	26		
THELINE, SE	CTION 36 TOWNSHIP 175	RANGE NMPN	//////////////////////////////////////
	12. County		
$\frac{1}{16}$	3,991' G	R	Lea ()))))))
Chec	k Appropriate Box To Indicate N	lature of Notice, Report or O	ther Data
NOTICE OF	INTENTION TO:	SUBSECUEN	T REPORT OF:
		308954024	TREPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	
TEMPORARILY ABANDON	C	COMMENCE DRILLING OPNS.	ALTERING CASING
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
OTHER		OTHER	
	[]		
17. Describe Proposed or Completed	Operations (Clearly state all next)		

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TEXACO Inc. has completed the following work on subject well:

- 1. Pull rods, pump and tubing.
- 2. Ran 3" frac tubing w/packer set at 4,002'. Frac open hole 4,093-4,710' w/30,000 gals gel brine in 3 10,000 gal stages w/1-1/2# sand/gal. Preceded 1st stage w/ 500 gals 15% NEA and 4,000 gals gel brine. Separate each stage w/500# rock salt, 500 gals gel brine and 250 gals 15% NEA. Swab well.
- 3. Run rods, pump & tubing, test and place on production.

18. I hereby certify that t	he information above is true and comple	ate to the best of my knowledge and belief.	
	allaid	Assistant District	DATE January 4, 1972
APPROVED BY	Orig. Signed by Joe D. Ramey Dist. J. Supy.	TITLE	DATE JAN - 6 1972

• •

$\{1,\dots,n\} = \{1,\dots,n\} = \{1,\dots,n\}$

.

-

,

JAN

OSL CONSELATOR