

FORMATION RECORD-Continued

FROM-	TO-	TOTAL FEET	FORMATION
-------	-----	------------	-----------

Well was abandoned at a total depth of 5000' with out any further testing by the original operator. The well was taken over by Mr. Ray Staley who plans to deepen it and will file a separate log for the deepening operation.

Recover 15 feet of drilling mud.
 Then 1 hour, fail to elicit blow for 5 minutes

NET 71 3732 - 3770

NO. 10

HISTORY OF OIL OR GAS WELL

It is of the greatest importance to have a complete history of the well. Please state in detail the dates of redrilling, together with the reasons for the work and its results. If there were any changes made in the casing, state fully, and if any casing was "sidetracked" or left in the well, give its size and location. If the well has been dynamited, give date, size, position, and number of shots. If plugs or bridges were put in to test for water, state kind of material used, position, and results of pumping or bailing.

10-43094-2 U. S. GOVERNMENT PRINTING OFFICE