

NO. OF COPIES RECEIVED
DISTRIBUTION
SANTA FE
FILE
DISPOS.
LAND OFFICE
OPERATOR

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☒ Fee ☐
1. Name of Operator Charles B. Read		5. State Oil & Gas Lease No. K-2299
2. Address of Operator P. O. Box 2126, Roswell, New Mexico 88201		7. Unit Agreement Name -
3. Location of Well UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 11 TOWNSHIP 19S RANGE 34E NMPM.		8. Farm or Lease Name State
4. Elevation (Show whether DF, RT, CR, etc.) 3989.5' KB		9. Well No. 1
10. Field and Pool, or Wildcat Quail Queen		11. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☒ CHANGE PLANS ☐ OTHER ☐	REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOB ☐ OTHER ☐	ALTERING CASING ☐ PLUG AND ABANDONMENT ☐ OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

To plug and abandon a depleted Queen oil well

To cut 5½" casing @ 2900'
To set 25 sx plug @ 3307' - 2917'
To set 25 sx plug @ 1860' - 1770'
To set 25 sx plug @ 103' - 363'
To set 10 sx plug @ 10' - 0'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <i>[Signature]</i>	TITLE Agent	DATE 9/14/70
APPROVED BY <i>[Signature]</i>	TITLE Agent	DATE SEP 21 1970
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

SEP 21 1970

OIL CONSERVATION COMM.
HOBBES, N. H.