

APPROVED

Form 9-331a
(Feb. 1951)


JAN 10 1963

Budget Bureau No. 42-R358.4.
Form Approved.

(SUBMIT IN TRIPLICATE)

E. W. STANDLEY
DISTRICT ENGINEERUNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

1883 000 0 00 0 4

Land Office New Mexico
Lease No. 056376
Unit Hescalero Ridge

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 3,

69

HESCALERO RIDGE UNIT

Well No. 3 is located 1980 ft. from XXX N line and 1980 ft. from XXX E line of sec. 2154/4 Sec 21 193 34.3 N
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)Quail Ridge-Bone Springs Lee New Mexico
(Field) (County or Subdivision) (State or Territory)The elevation of the derrick floor above sea level is 3734.3 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Well spudded 5:30 AM November 5, 1962. 8 5/8" casing set at 1897' with 500 sacks 6% gel and 100 sacks neat cement. Cement circulated. Drilled to total depth of 10,164'. Spotted 35 sacks cement plug at 9905'; 35 sack plug at 7000'; 35 sacks plug at 3400'; 35 sack plug at 1950' and 15 sack plug in top of 8 5/8" casing. Cleared location & erected steel marker.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Drilling & Exploration Company, Inc.Address Box 2075Hobbs, New Mexico

By _____

Title Division Production Manager