

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <i>20-025-02404</i>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E - 6005
7. Lease Name or Unit Agreement Name <i>Good code</i> Hudson State <i>6110</i>
8. Well No. 1
9. Pool name or Wildcat <i>Good code</i> Pearl Queen <i>49780</i>

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT'
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Mack Energy Corporation <i>13837</i>
3. Address of Operator P.O. Box 1359 Artesia, NM 88211-1359 (505) 748-1288	4. Well Location Unit Letter <i>K</i> : <i>1980</i> Feet From The <i>South</i> Line and <i>1980</i> Feet From The <i>West</i> Line Section <i>36</i> Township <i>19-S</i> Range <i>34-E</i> NMPM <i>Lea</i> County <i></i>
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set 5 1/2 C.I.B.P. at 4900' cap w/ 35' cement.
2. Load hole w/ mud.
3. Spot 25 sxs plug at base of salt 3420'.
4. Perferate 5 1/2 casing at top of salt 2000' squeeze w/ 50sxs and tag.
5. Perferate 5 1/2 casing at 164' 8 5/8 shoe - circulate cement to surface between 5 1/2 and 8 5/8 leaving 5 1/2 full. Set P&A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Raymond Maldonado* TITLE *Supervisor* DATE *1-17-96*
TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)
Orig. Signed by
Paul Kautz
Geologist

APPROVED BY DATE *JAN 17 1996*

CONDITIONS OF APPROVAL, IF ANY:

1.900 000 = 1.900 000

