DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-02406

5.	Indicate Type of L	STATE XX	FEE 🗌
6.	State Oil & Gas L	esse No.	
_	COOF 1		

1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No. E-6005-1	
SUNDRY NOTICES AND REPORTS ON WELLS		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS)	7. Lease Name or Unit Agreement Name	
1. Type of Well:  OIL  WELL  WELL  OTHER	Lea "K" State	
2. Name of Operator	8. Well No.	
Xeric Oil & Gas Company	1	
3. Address of Operator	9. Pool name or Wildcat Pearl (Seven Rivers, Sth)	
POB 51311, Midland, TX 79710  4. Well Location	reall (Seven Kivels, Son)	
Unit Letter _L : 1980 Feet Prom The South Line and 6	60 Feet From The West Line	
Service 36 Township 19-S Range 35-E	NMPM Lea County	
10. Elevation (Show whether DF RKB RT, GR. etc.)		
11. Check Appropriate Box to Indicate Nature of Notice	e, Report, or Other Data	
, , ,	SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK	· .	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL	LLING OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING CASING TEST AN	ID CEMENT JOB	
OTHER: OTHER.		
12. Describe Proposed or Completed Operations (Clearly state all perturent details, and give perturent dates, work) SEE RULE 1103.	including estimated date of starting any proposed	
The subject well has 8 5/8" Surface Casing surface and 5 1/2" casing set at TD. Top of cem is anticipated to begin immediately upon approva	nent @ 3300'. Plugging	
1. Previous CIBP set @ 4760' above Penrose 2. tag CIBP set @ 4250' (top of Queen) 3. Set CIBP @ 3850' (top of Seven Rivers)- 4. Set CIBP @ 1850' to cover salt - שׁנְבֹּׁנְ, 5. Set CIBP & Plug @ Surface	-spot 20 sx. of cement	
5/2 cs; @ 4780 TOC by TS 338	ee SO Farmer 30 A	
I hereby cardify that the information above is true and complete to the best of my knowledge and belief	your growing	
SIONATUREOperation	ns Manager 9/23/91	
TYPE OR PRINT NAME Gary 9. Barker	915-683-3171 TELEPHONE NO.	
(This space for State Use)		
ATROVED BY	DATE OF THE PARTY	

Will lave 100 on topof ret

THE COMMISSION MUST BE HOTISTED 24 HOURS PRIOR TO THE BECOMMING OF PLUGGING OPERATIONS FOR THE CHOS