

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-99

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	<b>30-025-02833</b>
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	<b>B-2423-4</b>
7. Lease Name or Unit Agreement Name	<b>EAST VACUUM GB/SA UNIT TRACT 1961</b>
8. Well No.	<b>001</b>
9. Pool name or Wildcat	<b>VACUUM GRAYBURG/SAN ANDRES</b>
4. Well Location	Unit Letter <b>E</b> : <b>1980</b> Feet From The <b>NORTH</b> Line and <b>660</b> Feet From The <b>WEST</b> Line Section <b>19</b> Township <b>17 S</b> Range <b>35 E</b> NMPM <b>LEA</b> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator <b>Phillips Petroleum Company</b>
3. Address of Operator <b>4001 Penbrook Street, Odessa, TX 79762</b>	6. Well No. <b>001</b>
4. Well Location Unit Letter <b>E</b> : <b>1980</b> Feet From The <b>NORTH</b> Line and <b>660</b> Feet From The <b>WEST</b> Line Section <b>19</b> Township <b>17 S</b> Range <b>35 E</b> NMPM <b>LEA</b> County	9. Pool name or Wildcat <b>VACUUM GRAYBURG/SAN ANDRES</b>
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: **ACIDIZED** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/26/94 MIRU DDU. COOH LD RODS AND PUMP. NU BOP.  
9/27/94 COOH W/TUBING. TRIP BIT AND SCRAPER TO 4362'. PU PKR TEST TBG IN HOLE. SET PKR AT 4334'. RU SWAB.  
10/03/94 RU AND PUMP 1000 GALS ACID. SWAB.  
10/04/94 RELEASE PKR COOH AND LD. GIH W/TBG. ND BOP. CHANGE OUT WELLHEAD.  
10/05/94 PU GIH W/PUMP AND RODS. RDMO DDU. MI TO SET UP PUMP.  
10/07/94 START PUMPING.  
01/14/95 PUMP 24 HRS TEST 9 BOPD 38 BWPD .6 MCF.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Paul Kautz* TITLE **SUPERVISOR, REG. AFFAIRS** DATE **01/17/95**

TYPE OR PRINT NAME **L. H. SANDERS** TELEPHONE NO. **915/368-1488**

(This space for State Use)

Orig. Signed by  
**Paul Kautz**  
Geologist

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE **JAN 19 1995**

CONDITIONS OF APPROVAL, IF ANY:

**RECEIVED**

JAN 1 8 1995

UCC HOSBS  
OFFICE