Submit 3 Copies To Appropriate District	State of New	`,		Form C		
Office District 1	Energy, Minerals and N	Natural Resource			Revised March 25	<u>, 1999</u>
1625 N. French Dr., Hobbs, NM 87240				API NO. 30-025-028	40	
District II 811 South First, Artonia, NM 87210		OIL CONSERVATION DIVISION			42	
811 South First, Artesia, NM 87210 District III	2040 South	2040 South Pacheco				
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, N	Santa Fe, NM 87505			FEE	
District IV 2040 South Pacheco, Santa Fe, NM 87505			6. State B-23	0il & Gas Lea 88	se No.	
SUNDRY NOTIO (DO NOT USE THIS FORM FOR PROP DIFFERENT RESERVOIR. USE "APPLI		e Name or Unit	Agreement Nam	ne:		
PROPOSALS.)				VACUUM GB/SA UNIT EAST		
1. Type of Well:			TRACT	TRACT 2060		
Oil Well 🕱 Gas Well 🗌 Other						
2. Name of Operator			8. Well	8. Well No.		
PHILLIPS PETROLEUM COMPANY						
3. Address of Operator				9. Pool name or Wildcat		
4001 PENBROOK STREET, ODESSA, TEXAS 79762				GRAYBURG/SAN	ANDRES	
4. Well Location						
Unit Letter <u>N</u> :	662 feet from the	SOUTH line	and 1983	feet from the	e <u>WEST</u>	line
Section 20	Township 17-	s Range 3	5-E NMPN	1 C	ounty LE2	1
Section 20 10 whimp 11 D 11 mgc 12 mgc 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3981' DF 3981' DF						
11 Check	Appropriate Box to Indi	cate Nature of	Notice, Report	, or Other Da	ta	
11. Check Appropriate Box to Indicate Nature of Notice, I NOTICE OF INTENTION TO: SUBS					RT OF	
	PLUG AND ABANDON	X REMEDIAL			LTERING CASIN	NG [
	CHANGE PLANS		E DRILLING OPN		LUG AND BANDONMENT	Ľ
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TE CEMENT JO	ST AND DB			
OTHER.						E

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Plug and Abandon Procedure, before and after wellbore schematics attached.

THE COMMISSION MUST BE NOTIFIED 24 PORCEASING OF THE BEGINNING OF POUGTUG OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE	K. M. J. TITLE SUPV., REGU	LATION/PRORATIONDATE_	11/26/01
Type or print name L. M. SANDERS	368-1667	Telephone No.	915/368-1488
(This space for State use)		*·	
	TITLE	DATE	

ЭЛЕГ ВЛ Conditions of approval, if any:

2 C 1

PHILLIPS PETROLEUM COMPANY PLUG AND ABANDON PROCEDURE EVGSAU # 2060-053 LEA COUNTY, NEW MEXICO

A. IMPORTANCE OF SAFETY

Safe operations are of utmost importance at all Phillips Petroleum Company properties and facilities. To further this goal, the Phillips Supervisor at the location shall request tailgate safety meetings prior to initiation of work and also prior to any critical operations. These tailgate meetings shall be attended by all Company, contract and service personnel then present at the location. All parties shall review proposed upcoming steps, procedures, and potentially hazardous situations. Occurrence of these meetings shall be recorded in the daily reports.

B. WELL CATEGORY

This is a **Category One** well because it is incapable of flowing gas a rate greater than 500 MCFD and the H2S concentration is less than 100 ppm. For a **Category One** well the barrier requirements are one untested barrier. Rule 118 does not apply.

C. BOP CLASS AND EXCEPTIONS

The MPSP for this well is estimated to be less than 1000 psig. The H2S concentration is less than 100 ppm. Therefore, a **Class One Manual BOP** is required. It will consist of a mechanically operated blind ram on bottom with a pipe ram on top. Emergency pump connections will be 1 inlet between the dual rams and 1 inlet between the blind rams. Each inlet will have 1 valve only. A choke manifold is not required.

APPROVALS:

Drilling Engineer:	 DATE:
Drilling Superintendent:	 DATE:
Operations Manager:	 DATE:

· • •

PLUG AND ABANDON WELL PROCEDURE EVGSAU #2060-053

- **NOTE:** Cement used is Class "C", density of 14.8 ppg, yield of 1.32 cubic feet per sack. **NOTE:** See 08/07/01 drilling report.
 - Before rigging up, dig a plastic-lined channel/pit to confine displaced wellbore fluids during operations.
- 1. Notify NMOCD at (505) 393-6161, 24 hours prior to initiating plugging operations.
- 2. GIH w/ 2-3/8" WS open-ended and tag CIBP @ 4003'. Circulate 5-1/2" casing with 9.5 ppg mud-laden fluid.
- 3. Spot Plug No. 1, minimum 25 sx., calculated interval: 4003'-3762'. The plug will cover the Glorieta, San Andres, and Queen.
- 4. POOH & LD to 3275'. Spot Plug No. 2, 40 sx. (minimum 25 sx.), calculated interval: 3275'-2980'. The plug will cover the 7 Rivers and Yates.
- 5. POOH & LD to 1860'. Spot Plug No. 3, 30 sx. (minimum 25 sx.), calculated interval: 1860'-1571'. The plug will cover the casing shoe and Rustler. $\frown TAG$
- 6. POOH & LD to 140'. Spot Plug No.4, 15 sx. (minimum 10 sx.), calculated interval: 140'-surface. Serves as the surface plug.
- 7. POOH & LD workstring. Top off if necessary. WOC & visually tag.
- 8. Install dry hole marker. Perform reclamation work.
- 9. Send forms and reports to:

Phillips Regulatory 4001 Penbrook Odessa, Texas 79762

PHILLIPS PETROLEUM COMPANY - PERMIAN PROFIT CENTER EVGSAU 2060-053

Date: November 20, 2001



W. Negrey 11/20/01

WELLBORE SKETCH "ILLIPS PETROLEUM COMPANY - PERMIAN PROFIT CENTER EVGSAU 2060-053

Date: November 20, 2001



W. Negrey 11/20/01