

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO. 30-025-02842
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2388

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name:  EAST VACUUM GB/SA UNIT TRACT 2060
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	8. Well No. 053	
2. Name of Operator Phillips Petroleum Company	9. Pool name or Wildcat VACUUM GRAYBURG/SAN ANDRES	
3. Address of Operator 4001 Penbrook Street Odessa, TX 79762		
4. Well Location  Unit Letter <u>N</u> : <u>1983</u> feet from the <u>WEST</u> line and <u>662</u> feet from the <u>SOUTH</u> line  Section <u>20</u> Township <u>17S</u> Range <u>35E</u> NMPM County <u>LEA</u>		
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3981' DF		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: CLEAN OUT, TEST, SET CIBP TO P&A <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

08/07/01 MIRU DDU COOH W/RODS/EMP ND WH NU BOP COOH W/TBG GIH W/CSG SCRAPER & TBG  
COOH W/TBG & SCRAPER GIH W/RBP & PKR & SET RBP @ 4165' TST CSG FOUND HOLE  
27' F/SURF COOH W/PKR MIRU HES RUN CSG INSPECTION LOG & CMT BOND LOG RDMO  
HES DIG OUT CELLAR COLD CUT CSG HANGER OFF MIRU ROTARY WL & FREEPOINT CSG  
CSG FREE 9' F/SURF RD ROTARY WL RU SMITH SERVICES & WASH OVER 5-1/2 CSG TO  
65' F/SURF RD SMITH RU ROTARY WL & TRY T/BK OFF CSG @ 63' F/SURF CSG TWISTED  
OFF 55' F/SURF RD ROTARY WL GIH W/TBG & LATCH ON T/RBP COOH W/TBG & RBP GIH  
W/CIBP & SET @ 4003' COOH LD TBG & RODS.

08/20/01 RDMO DDU - WELL TO BE P&A'D - COMPLETE DROP F/REPORT.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE SUPVR., REGULATION/PRODUCTION DATE 11/07/2001  
Type or print name LARRY M. SANDERS Telephone No. 915/368-1488

(This space for State use)

APPROVED BY [Signature] TITLE PETROLEUM ENGINEER DATE 11/20/2001  
Conditions of approval, if any: