

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. <b>30-025-02858</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <b>B-2735</b>
7. Lease Name or Unit Agreement Name <b>EAST VACUUM GB/SA UNIT TRACT 2271</b>
8. Well No. <b>002</b>
9. Pool name or Wildcat <b>VACUUM GB/SA</b>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3939' GR</b>

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator <b>Phillips Petroleum Company</b>
3. Address of Operator <b>4001 Penbrook Street, Odessa, TX 79762</b>	4. Well Location Unit Letter <b>P</b> : <b>660</b> Feet From The <b>SOUTH</b> Line and <b>660</b> Feet From The <b>EAST</b> Line Section <b>22</b> Township <b>17 S</b> Range <b>35 E</b> NMPM <b>LEA</b> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3939' GR</b>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: **SWAB TESTED** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/01/94 MIRU DDU. COOH LD RODS AND PUMP. NU BOP AND START OUT OF HOLE W/TBG.  
11/02/94 MIRU PU GIH W/TBG. RDMO SET PKR @ 4248'. LOAD AND TEST CSG TO 500# OK. RU SWAB.  
11/03/94 SWABBED.  
11/04/94 TAG FILL AT 4443'. CIRCULATED CLEAN.  
11/08-11/10 CLEANED OUT.  
11/11/94 SWABBED.  
11/15/94 RELEASED THE PKR COOH. GIH W/ TBG TO 4390'. ND BOP. SWABBED.  
11/16/94 PU GIH W/PUMP AND RODS. RD MO DDU.  
02/03/95 PUMP 24 HRS TEST 3 BOPD, 6 BWPD, AND 1 MCF.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *L. M. Sanders* TITLE SUPERVISOR, REG. AFFAIRS DATE 02/20/95

TYPE OR PRINT NAME L. M. SANDERS TELEPHONE NO. 915/368-1488

(This space for State Use)

ORIGINAL SIGNED BY  
GARY WINK  
FIELD REP II

FEB 23 1995

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: