

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
P.O. Box 1000, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-02863
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	R-2531
7. Lease Name or Unit Agreement Name	EAST VACUUM GB/SA UNIT TRACT 2469
8. Well No.	001
9. Pool name or Wildcat	VACUUM GB/SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3903' GL	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Phillips Petroleum Company
3. Address of Operator 4001 Penbrook Street, Odessa, TX 79762	4. Well Location Unit Letter M : 330 Feet From The SOUTH Line and 660 Feet From The WEST Line Section 24 Township 17 S Range 35 E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3903' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU. NU BOP. SET CIBP AT 4200'.
2. SPOT PLUG NO. 1 (25 SX CMT) 4200'-4100'. COVERS GB/SA.
3. PERFORATE CSG AT 2977'. SQZ UNDER PKR W/PLUG NO. 2 (50 SX CMT) 2977'-2877'. COVERS THE YATES.
4. PERFORATE CSG AT 1562'. SQZ UNDER PKR W/PLUG NO. 3 (75 SX CMT) 1562'-1450'. COVERS THE SALT TOP AND THE SURFACE SHOE.
5. PERFORATE CSG AT 400'. PUMP PLUG NO. 4 (135 SX CMT) DOWN CSG, THRU PERFORATIONS 400' AND BACK TO THE SURF. ON ANNULUS, LEAVING CSG FULL.
6. CUT OFF CSG 3' BELOW GROUND LEVEL. INSTALL MONUMENT MARKER. PERFORM RECLAMATION WORK.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

[Signature]

TITLE SUPERVISOR, REG. AFFAIRS

DATE 4/11/95

TYPE OR PRINT NAME L. M. SANDERS

TELEPHONE NO 915/368-1488

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

APR 14 1995
DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 18 1966
U.S. AIR FORCE
OFFICE

100-100000

100-100000
100-100000