<u> </u>	• ••• •••	
Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Dep	Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION		SION WELL API NO.
DISTRICT II Santa Fe, New Mexico 87504-2088		20-025-02004
P.O. Drawer DD, Artesia, NM 88210 Sania Fe, New Mexico 87504-2088		5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		STATE X FEE 6. State Oil & Gas Lease No. B-1839
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESEI (FORM C	ICES AND REPORTS ON WELLS DPOSALS TO DRILL OR TO DEEPEN OR PLUG BA RVOIR. USE "APPLICATION FOR PERMIT" -101) FOR SUCH PROPOSALS.)	
1. Type of Well: OE GAS WELL X WELL	OTHER	East Vacuum Gb/SA Unit Tract 2738
2. Name of Operator Phillips Petroleum	Company	8. Well No. 002
3. Address of Operator		9. Pool name or Wildcat
4001 Penbrook Stree	et, Odessa, Texas 79762	Vacuum Gb/SA
Section 27	30 Feet From The North Line as Township 17-S Range 35-E 10. Elevation (Show whether DF, RKB, RT, Control of the state) 10. Elevation (Show whether DF, RKB, RT, Control of the state)	NMPM Lea County
11. Check	Appropriate Box to Indicate Nature of N	
 work) SEE RULE 1103. 1. MIRU DDU. Instal same. 2. RIH with RBP and 	CASING TE <u>n to minimize CO</u> 2 X OTHER: <u>tions (Clearly state all pertinent details, and give pertinent</u> <u>1 annular BOP.</u> POOH with st	E DRILLING OPNS. PLUG AND ABANDONMENT ST AND CEMENT JOB
3. RIH with 2-7/8" p	roduction tubing and bottom	hole assembly.
4. Load csg-tbg annu Set packer at <u>+</u> 41	lus w/67 bbls 10 ppg brine o 00'.	containing 1.5% Unichem TH-370.
5. RDMO DDU		(Over)
	e and complete to the best of my knowledge and bellef. Marco <u>TITLE</u> Supv.	Regulatory Affairs 10/6/92
TYPE OR FRENT NAME L. M. San	ders	915/ Telephone no. 368–1488
(This space for State Use)		OCT 1 4 '92
APTROVED BY		
CONDITIONS OF APPROVAL, IF ANY:		

- 6. Leave well shut-in until wellhead pressure reaches above 500 psi. At this point the well can be opened up to flow; however, do not flow well at a rate greater than 300 MCFD and do let flowing wellhead pressure drop below 500 psi.
- 7. Move the Centrilift 200 KVA step-up transformer and VSD to 3440-002 and install same there.

.