

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	WELL API NO. 30-025-02924
2. Name of Operator Phillips Petroleum Company	5. Indicate Type of Lease STATE ☒ FEE ☐
3. Address of Operator 4001 Penbrook Street Odessa, TX 79762	6. State Oil & Gas Lease No. B-1399-1
4. Well Location Unit Letter <u>O</u> : <u>660</u> feet from the <u>SOUTH</u> line and <u>1980</u> feet from the <u>EAST</u> line Section <u>29</u> Township <u>17S</u> Range <u>35E</u> NMPM County <u>LEA</u>	7. Lease Name or Unit Agreement Name: EAST VACUUM GB/SA UNIT TRACT 2913
8. Well No. 001	
9. Pool name or Wildcat VACUUM GRAYBURG/SAN ANDRES	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3964' GL 3989' RKB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐	REMEDIAL WORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐	CASING TEST AND CEMENT JOB ☐
OTHER: ☐	OTHER: ACIDIZE & RETURN T/PRODUCTION ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion, or recompilation.

03/08/02 MIRU IDU KILL WELL COOH W/RODS & PMP ND WH NU BOP COOH W/TBG
03/09/02 KILL FIN COOH W/TBG GIH W/SANDIN BLR & TAG F/FILL @ 4375' 290' FILL COOH W/SANDIN BLR MIRU
SMITH RU GIH W/BIT COLLARS & TBG SD DUE T/HI WINDS
03/10&11/02 CREW OFF
03/12/02 KILL FIN GIH W/BIT COLLARS & TBG CO FILL F/4375-4655' RD SMITH RU COOH W/TBG COLLARS & BIT
03/13/02 KILL FIN COOH W/TBG COLLARS & BIT GIH W/BIT SCRPR & TBG T/4190' COOH W/TBG SCRPR & BIT GIH W/
TP PKR & TBG TSTNG T/5000 PSI RU PMP TRK PMP 750 GAL TOLUENE RD PMP TRK COOH W/7 STDS TBG
SET PKR 3686' EOT 4185'
03/14/02 OPEN T/FRAC TK SWAB BK TOLUENE REL PKR GIH W/7 STDS TBG RU PMP TRK PMP 750 GAL MIX SCALE
CONVERTER RD PMP TRK COOH W/8 STDS TBG SET PKR 3624' EOT 4123' TST CSG 500 PSI OK
03/15/02 MIRU HES TST LNS T/6400 PSI PMP 50 BBL FW PAD @ 4 BPM 475 PSI PMP 500 GAL 15% FERCK ACID 5 BPM
1249 PSI PMP 4300# RKSALT 4300# 100 MESH SALT 5.1 BPM 1300 PSI PMP 3000 GAL 15% FERCK 4.7 BPM
(CONTINUED ON BACK)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Larry M. Sanders TITLE SUPVR., REGULATION/PRORATION DATE 4/5/02

Type or print name LARRY M. SANDERS Telephone No. 915/368-1488

(This space for State use)

APPROVED BY W. J. KAUTZ TITLE ENGINEER DATE APR 11 2002

Conditions of approval, if any:

03/15/02 CONTINUED

1935 PSI PMP 250# RKSALT & 250# 100 MESH @ 5 BPM 2546 PSI PMP 1400 GAL 15% FERCK @ 5.5 BPM 2133
 PSI PMP 350# RKSALT & 350# 100 MESH 4.9 BPM 2544 PSI PMP 1100 GAL 15% FERCK ACID 5.5 BPM 2135 PSI
 PMP 100 BBL FW FLUSH 4.2 BPM 2432 PSI STOP PMPG ISIP 2126 PSI 5 MIN 2042 10 MIN 1998 15 MIN 1940
 PSI AVG RATE 4 BPM AVG PRESS 2880 PSI MIN RATE 0.4 BPM MAX RATE 5.5 BPM MIN PRESS 948 PSI MAX
 PRESS 5200 PSI PRESS INCR ON #1 BLK 3832 PSI #2 BLK 1500 #3 2212 PSI RDMO HES LEAVE SI 1 HR OPEN
 T/FRAC TK SWAB BK LD RU PMP TRK PMP 150 BBL FW DWN TBG RD PMP TRK SISD
 03/16/02 OPEN UP T/FRAC TK SWAB REC 84 BBL GIH W/TBG TAG SALT 4574' RU PMP TRK PMP FW CO T/TD COOH W/TBG
 PKR & TP RUN KS

03/17&18/02 CREW OFF

03/19/02 KILL COOH W/KS GIH W/SANDLN BLR & TAG FILL @ 4550' COOH W/SANDLN BLR GIH W/NOTCHED COLR & TBG RU
 PMP TRK CO SALT T/4632' COOH W/TBG & NOTCH CLR GIH W/PROD TEG ND BOP NU WH

03/20/02 BLD OFF TBG GIH W/PMP & RODS WO ELEC WO GANG T/PLUMB WH HANG ON LD & TST PUT WELL ON PROD TOO
 WINDY T/RD

03/21/02 CLN LOC RDMO DDU WELL ON PROD -- DROP F/REPORT