

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Alamo, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-26397	
1. Indicate Type of Lease STATE ☒ FEE ☐	
4. State Oil & Gas Lease No. B-2433-12	
7. Lease Name or Unit Agreement Name East Vacuum Gb/SA Unit Tract 2963	
8. Well No. 002	
9. Pool name or Wildcat Vacuum Gb/SA	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street, Odessa, Texas 79762	
4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>West</u> <u>Line</u> and <u>1980</u> Feet From The <u>South</u> <u>Line</u> Section <u>29</u> Township <u>17-S</u> Range <u>35-E</u> NMMPM <u>Lea</u> County <u></u>	
10. Elevation (Show whether DP, RKB, RT, GR, etc.) <u>3977'</u> RKB - <u>3969'</u> GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: Clean-out Stimulate & Reactivate ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-18-91: MIRU DDU. NU BOP. Trip sand pump. Tag @ + 4750'. Catch sample of formation.

10-19-91: Pick up 2-7/8" workstring tbq. & GIH w/5-1/2" scraper & 4-3/4" bit to 4320'. COOH. GIH w/5-1/2" pkr & set @ 4201'. Load and test tbq/csg annulus to 500#. RU swab - FL @ 1100' SD. Pump 3000 gal 15% NEFe HCl acid w/LST.CS 5% TW-425, 3000# rock salt in 52 bbl gelled brine, and 37 bbl 2% KCl flush. 1000 gal acid, 1500# salt in 27 bbl brine; 1000 gal acid; 1500# salt in 25 bbl brine; 1000 gal acid; 37 bbl flush. Open well up w/tbg on voc & FL @ Sur. Swab.

10-22-91: Open up well w/100# on tbq.

10-23-91: Open up well w/90# on tbq. Swab.

10-24-91: Open up well w/90# on tbq. GIH w/swab. Pump 145 bbl w/FL @ 800' and 2% oil cut. Unset pkr. COOH LD tbq & pkr. Temp. drop from report.

I hereby certify that the information shown is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Supervisor Reg/Proration DATE 4-1-92

TYPE OR PRINT NAME L. M. Sanders (915) TELEPHONE NO. 368-1488

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

COMMENTS OF APPROVAL, IF ANY: