STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

40. 07 COPICS SCCCIVES		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.1.		
LAHO OFFICE		
OPERATOR	1	

OIL CONSERVATION DIVISION

	OX 2088 W MEXICO 87501	Form C-103 Revised 10-1-7	
U.S.G.S.		5a. Indicate Type of Lease	
LAND OFFICE		State Fee	
OPERATOR		5, State Oil 6 Gas Luase No.	
SUNDRY NOTICES AND PEROPES OF	N WELLS	1757586	
SUNDRY NOTICES AND REPORTS OF THE OF	N TELLO BACK TO A DIFFERENT RESERVOIR, UCH PROPOSALS,)		
I. OIL GAS		7. Unit Agreement Name	
2. Name of Operator		Central Vacuum Unit	
TEXACO Inc.		8. Farm or Lease Name	
3, Address of Operator		Central Vacuum Unit	
P. O. Box 728, Hobbs, New Mexico 882	240	8	
		Vacuum Grayburg	
UNIT LETTER H ,660 FEET FROM THE FAST	LINE AND <u>2310</u> FEET FROM	Vacuum Grayburg	
THE North LINE, SECTION 30 TOWNSHIP 17-5	RANGE 35-E NMPM.		
15. Elevation (Show whether	r DF, RT, GR, etc.,	12. County	
3976' (0	R)	Lea	
Check Appropriate Box To Indicate	Nature of Notice, Report or Otl	her Data	
NOTICE OF INTENTION TO:	SUBSEQUENT	REPORT OF:	
PERFORM REMEDIAL WORK	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING CHANGE PLANS	CASING TEST AND SEMENT JOB		
OTHER	OTHER	[_]	
17. Describe Proposed or Completed Operations (Clearly state all pertinent de- work) SEE RULE 1103.	tails, and give pertinent dates, including	estimated date of starting any proposed	
1. Rigged up. Pull production equip	ment.		
2. Set pkr. @ 4154'. Acidize perfs	4284' - 4624' w/6000	gals. 15% HCL Acid.	
riusned w/40 Bbis. KCL Wtr.	•		
3. Install pumping equipment. Test &	return to production	n.	
6. I hereby certify that the information above to true and complete to the best of	of my knowledge and belief.		
7///			
IGHED MICHAEL TITLE A	sst. Dist. Mgr.	DATE 6-3-81	
——————————————————————————————————————			
\$ 1.3 miles 100		\$ 84 1 0 10 7g	
PPROVED BY TITLE		DATE	