

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-02952
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	857943
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	3
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES

<p align="center">SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>	
1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	<p>Unit Letter <u>C</u> : <u>330</u> Feet From The <u>NORTH</u> Line and <u>1650</u> Feet From The <u>WEST</u> Line</p> <p>Section <u>30</u> Township <u>17S</u> Range <u>35E</u> NMPM <u>LEA</u> COUNTY</p>
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐
 OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
 COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER: ☐ CLEANOUT & ACIDIZE ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-24-98: MIRU. TOH W/RDS & PUMP. NDWH. NUBOP.
 6-25-98: WELLCHECK 145 JTS TBG OUT OF HLE. RU REV UNIT. TIH W/BIT & DC'S ON 2 3/8" TBG TO 4150'.
 6-26-98: C/O O.H. FR 4630-4724' (TD). TOH. LDDC'S.
 6-29-98: TIH W/PKR ON 2 3/8" TBG. TEST TO 5000#. COULD NOT TEST LAST 29 JTS DUE TO PARAFFIN BUILD UP IN TBG. TIH W/PARAFFIN KNIFE & CUT PARAFFIN. TIH W/129 JTS 2 3/8" TBG. TRY TO SET PKR @ 4107'. WOULD NOT SET. PULL & PSA 4077'. LOAD & TEST CSG TO 500#-OK. ACIDIZE 4 3/4" O.H. FR 4209-4724' W/10,000 GALS 15% NEFE HCL W/6500 # RK SLT. RU SWAB. START FL @ 400'. END FL @ 1500'.
 6-30-98: BLED OFF IN 10 MINS. TIH W/PARAFFIN KNIFE. CUT PARAFFIN. RU SWAB. START FL @ 2400'. END FL @ 3800'. RD SWAB., RU PUMP TRUCK. SCALE SQUEEZE 4209-4724' W/55 GALS TH-756 MIXED IN 15 BFW. FLSH W/100 BFW.
 7-01-98: REL PKR. TOH W/TBG & PKR. TIH OPEN ENDED W/149 JTS 2 3/8" TBG. TAG SALT FILL @ 4673'. TOH W/TBG. TIH W/OPSMA, SN, TBG. MA @ 4644'. SN @ 4613'. TAC @ 4072'. NDBOP. NUWH. TIH W/GAS ANCHOR, & PMP & RDS. HANG ON WELL. TEST TBG TO 500#-OK. RIG DOWN. PUMPING & TESTING.
 7-10-98: ON 24 HR OPT. PUMPED 17 BO, 66 BW, & 2 MCF.
 FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 10/1/98

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED BY WILLIAMS TITLE

DATE NOV 10 1998

CONDITIONS OF APPROVAL, IF ANY: