STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

40. 67 (02)(8 ACCEIVED	1	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR	7-	

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION

SANTA FE	P. O. BOX 2088	Revised 10-1-7
FILE	SANTA FE, NEW MEXICO 87501	
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
Во поставляння выполнення в на должно дом на поставляний на поставляний на поставляний на поставляний на поста В поставляний на пост	•	B-1713
SUNDR	Y NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PRO USE "APPLICAT	Y NOTICES AND REPORTS ON WELLS POSALS TO DAILL ON TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ICH FOR PERMIT -11 (FORM C-101) FOR SUCH PROPOSALS.)	
1.		7. Unit Agreement Name
WELL XX WELL	OTHER-	Central Vacuum Unit
2. Name of Operator		8. Form or Lease Name
Texaco Inc.		Central Vacuum Unit
3, Address of Operator		9. Well No.
P.O. Box 728, Hobbs	New Mexico 88240	64
4, Location of Well	New Mexico Co240	- ·
D 10	780 Nombo 7000	Vacuum Grayburg
UNIT LETTER L	980 FEET FROM THE North LINE AND 1980 FEET FRO	
Wood	27 2 2 2 2	
THE WEST LINE, SECTIO	N 31 TOWNSHIP 17-S RANGE 35-E NMPH	
mmmmmmm		
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Lea \\\\\\\\
Check A	Appropriate Box To Indicate Nature of Notice, Report or O	ther Data
NOTICE OF IN		T REPORT OF:
•	300024021	TREFORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANCON		ALTERING CASING
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
TOTAL CHARLES	Boned m Linto	r Flow
OTHER	OTHER REPAIR WALE	r F.TOM X
VIII.	,	
17. Describe Proposed or Completed Op-	erations (Clearly state all pertinent details, and give pertinent dates, including	g estimated date of starting any proposed
work) SEE RULE 1 103.		o and any proposed
l. Rigged up. Pul	ll rods & pump. Install BOP. Pull tubi	n a
	12 1000 % bamb. THE CALL DOL! LATE CADE	118.
2. Set RBP @ 3960	& spot 20' Sand on plug. Test casing.	The hale he was
Radio Active Su	wish spot so, parid ou bing. Test castus.	onable to run
Hadro Active St	arvey.	
3. Perforate 7" Cs	16 11/2 IS @ 15001 Gament	0.75554 /555
Ow Class III!	sg. w/2-JS @ 1500'. Cement squeeze perf	8. @ 1500' w/500
Mon of Coment (Tement containing 2% CaCl. Run Temperat	ure Survey.
rop or cement @	470'. WOC. DOC. Test reveals Water	Flow.
h ont named out	t o sheet o	
4. Set cement reta	iner @ 1411'. Cement squeeze 7" Csg. p	erfs. @ 1500'
W/DUU SX. Class	i 'C' Cement containing 2% CaCl & 2000 w	ale Flachak Dan
Temperature sur	vey. Top of Cement @ 300', Woc. Doc	Test csg. to 750#
for 30 minutes,	3:15-3:45 PM, 5-19-2. Tested OK.	
5 6 5"		
5. Open 7" Csg., h	ad Water Flow.	
	•	
18. I hereby certify that the information a	bove is true and complete to the best of my knowledge and belief.	
>∀ ,1,1,1,1/1	Anni Ment se	6 03 00
SIGHED / WWW	Asst. Dist. Mgr.	DATE 6-21-82
OMGRA! SE	3.3.84	
JERRY SEXT	- 1. So. 4	

JUN 22 1982

MOBBS OFFICE