

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-02954
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-387
7. Lease Name or Unit Agreement Name	
Central Vacuum Unit	
8. Well No.	75
9. Pool name or Wildcat	Vacuum Grayburg San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator
Texaco Exploration and Production Inc.
3. Address of Operator
P.O. Box 730 Hobbs, New Mexico 88240

4. Well Location
Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line
Section 31 Township 17-S Range 35-E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3990' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/29/92 - 8/3/92

1. MIRU. C/O from 4660' to 4710'. Sptd 500 gal ammonium bicarbonate fr 4333'-4660', set pkr @ 3940', sqzd into form w/ 500 gal ammonium bicarbonate. Spt 500 gal 15% NEFE fr 4333'-4660', set pkr @ 3940' & sqzd into form w/ 600 gal 15% NEFE.
2. Acidized OH fr 4330'-4660' w/ 10000 gals 15% HCL NEFE, & 8000# RS in 4 stages w/ 2000# RS between stages. Flushed w/ FW. Max P = 4000#, AIR = 4.7 BPM. Swabbed load back.
3. Scale sqz w/ 5 drums TH-493 in 60 BFW, overflushed w/ 500 BFW. Returned well to prod.

OPT 8-11-92 49 BOPD, 888 BWPB, 18 MCF

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M.C. Duncan TITLE Engineer's Assistant DATE 8-15-92
TYPE OR PRINT NAME M.C. Duncan TELEPHONE NO. 393-7191

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE AUG 19 '92
CONDITIONS OF APPROVAL, IF ANY: