

MISCELLANEOUS NOTICES

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commissioner or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of notice by checking below:

NOTICE OF INTENTION TO TEST CASING SHUT-OFF	<input checked="" type="checkbox"/>	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL
NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING
NOTICE OF INTENTION TO REPAIR WELL		
NOTICE OF INTENTION TO DEEPEN WELL		NOTICE OF INTENTION TO PLUG WELL

Midland, Texas

April 18, 1939

Place

Date

OIL CONSERVATION COMMISSION,
Santa Fe, New Mexico.

Gentlemen:

Following is a notice of intention to do certain work as described below at the **Humble Oil & Refining Company** N. M. State "K" **5** SE/4 of NE/4
Company or Operator **32** 17-South **35** East **Lease** Well No. **5** in **SE/4 of NE/4**
of Sec. **32**, T. **17-South**, R. **35-East**, N. M. P. M., **Vacuum** Field,
Lea County.

FULL DETAILS OF PROPOSED PLAN OF WORK
FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS OF THE COMMISSION

SET CASING AS FOLLOWS:

SIZE	WEIGHT	AMOUNT	SET AT	FORMATION	DEPTH OF WELL	NO. SACKS & MAKE OF CEMENT	PLUG ON BOTTOM
10-3/4"	40.5#	247'	261'	Red Beds	272'	125 Sacks El Toro	5:00 P.M. 4/17/39

Halliburton method used.

Will test by bailing dry & drill plug on April 19, 1939.

Approved _____, 19____
except as follows:

HUMBLE OIL & REFINING COMPANY

Company or Operator

By

Position

Division Chief Clerk

Send communications regarding well to
J. W. House

Name

Address

Box 1600 - Midland, Texas.

OIL CONSERVATION COMMISSION,

By

Title

OIL & GAS INSPECTOR