	E OF NEW MEXICO MINERALS DEPARTMENT					
		LCONSERVA	TION DIVISION			
DISTRIBUTION P. O. BOX 2088				Form C-103		
SANTA FE SANTA FE, NEW MEXICO 87501					Revised 10-1-78	
FILE.				Sa. Indicate Type	at Leuse	
U.S.G.1		•		State X	Fee	
OPERA				5. State Oll & Gas	Lease No.	
API No. 30-025-02969				<u>A-1320</u>		
SUNDRY NOTICES AND REPORTS ON WELLS - (DO NOT USE THIS FORM FOR PAGPASALS TO DRILL ON TO DECEDEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPUSALS.)						
I. OIL GAB OTHER-				7. Unit Agreement East Vacuu GB/SA Unit	East Vacuum GB/SA Unit	
2, Dunin of Operator				B. Form or Lease East Vacuu	m GB/SA	
Phillips Petroleum Company J. Address of Operator				Unit, Trac 9. Well No.	Unit, Tract 3202	
Room 401, 4001 Penbrook Street, Odessa, Texas 79762				015		
4. Location of Well					10. Field and Pool, or Wildcat	
UNIT LETTER 0 663 FEET FROM THE SOUTH LINE AND 1980 FEET FROM				Vacuum GB/		
тис	East LINE, SECTION 32	TOWNSHIP 17-5	<u>ванде 35-Е</u> нмрм.			
	mmmmmm	(St. 1.1		12. County	£}}}}}}	
SHHH	//////////////////////////////////////	Elavation (Show whether				
<u></u>	Munnin	<u>3968' RK</u>		Lea	011111111	
	Check Appropriate NOTICE OF INTENTION 1		lature of Notice, Report or Otl SUBSEQUENT	her Data F REPORT OF:		
	C-1				[]	
PERFORM REM	E E E E E E E E E E E E E E E E E E E	PLUG AND ABANDON	COMMENCE DRILLING OPNS.			
TEMPORARILY	74	CHANGE PLANS	CASING TEST AND CEMENT JOB		ID ABANDONMENT	
			OTHER	-		
OTHER						
	Froponed or Completed Operations (Clear RULE 1103.	ly state all pertinent det	ails, and give pertinent dates, including	estimated date of s	tarting any proposed	
•			1		c · · 1	
4-24-80 MI Well Service Unit. Attempted to pull rods and pmp rds parted, unable to fish.						
Attempted to pull tubing. Tubing stuck. 4–25–80 Worked tubing 8 hours, unable to pull.						
4-25-80 Worked tubing o hours, unable to pure. 4-26-80 McCullough ran wire line, cut tubing at 1425'. Pulled and left 3000' tubin					g in hole	
	with top of fish at 1425				6 111 11010	
4-27-29-	-					
80						
5-1-80						
5-2-80 Ran tubing and 4-3/4" mill. Milled on fish to 1447-1448'.						
5-3-80						
5-4-80						
5-5-80		1 1429-1431'. 5	-1/2" casing parted. La	id down 1431	' of 5-1/2"	
	casing.	· _ · · · ·				
5-6-80 Ran 6-3/4" mill. Milled 5-1/2" casing to 1431-1436'.						
5-7-80 Milled casing to 1436-1438'. COOH. Ran 6-5/8" impression block. 6-3/4" mill. Milled casing to 1438-1440'.				k. No impri	nt. Ran	
5-8-80		•	'0'. '2" casing from 1440–1445	۰.		
	-	,	(OVER)			
	reinstate allowable".	ind complete to the best				
or and Ref.	J. Roper FW. J. Mueller	<u>nrccSeni</u>	or Engineering Specialis	t DATE May 2	8,1980	
	0.42 To T 🎙			R al	5 SAU	
APPROVED BY _	inter interes			DATE STATE	·	
CONDITIONS	OF APPROVAL THANY					
• _	.*					

- 5-9-80 Milled 5-1/2" casing at 1447'.
- 5-10-80 Milled 1445' to 1447'.
- 5-11-80 Pulled mill. Ran new mill.
- 5-12-80 Ran magnet on tubing to 4545', pulled magnet, no rec. Ran dress off mill to 1445'. Dressed off fish 1445-1448'.
- 5-13-80 Running tubing and string swedge. Pulled tubing and dress-off mill. Ran tubing and overshot to 1448', caught tubing and rec. all tubing.
- 5-14-80 Prep to back off 5-1/2" casing. Ran string swedges. Swedged out 5-1/2" casing at 1450'. Pulled swedges, ran spear, caught 5-1/2" casing at 1450'.
- 5-15-80 Dropped 800' tubing spear bottom, ran tubing, speared into fish, pulled 3500'.
- 5-20-80 Ran 2-3/8" tubing and 4-3/4" bit to 4361'.
- 5-21-80 Cleaned out to 4650'. Pulled tubing and bit. Ran tubing and BP, set BP at 1587'.
- 5-22-80 Set E-Z drill ret at 1375'. Cemented thru casing patch at 1450' with 300 sacks Class "C" with 2% CaCl₂. Flushed with 5 BW. Cement circd. Squeezed 80 sacks in formation, reversed 2-1/2 sacks. WOC 19 hours.
- 5-24-80 Drld retainer at 1375' and washed sand off BP.
- 5-25-80 Ran tbg and retrieving tool, fished BP. Reran tbg. 146 jts 2-3/8", set at 4500'. Set 2" x 1-1/4" x 12' pmp at 4499'. MO Well Service Unit.

JUH 2 1330

 $Q_{2,1}^{\rm eq} <_{\rm eq} <_{\rm$