		D G. 102
NO. OF COPIES RECEIVED		Form C-103 Supersedes Old
		C-102 and C-103
DISTRIBUTION	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
SANTA FE	11001.3 Unit of b. G. G.	
FILE		5a. Indicate Type of Lease
U.S.G.S.	Aug 8 11 40 AM '67	State X Fee
LAND OFFICE		5. State Oil & Gas Lease No.
OPERATOR	i	A-1320
SUNDR	Y NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PRO	Y NOTICES AND REPURIS OIN WELLS person reservoir. Prosals to Drill or to Despen or Plug Back to a Different reservoir. For such proposals.) ION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
1		_
OIL X GAS OTHER-		8. Form or Lease Name
2. Name of Operator		New Mexico "K" State
Humble Oil & Refining Company		
		9. Well No.
3. Address of Operator		17
Box 1600, Midland, Texas 79701		10. Field and Pool, or Wildcat
4. Location of Well	330	Vacuum Glorieta
P	330 S LINE AND FEET FR	IIIIIIIIIIIII
UNIT LETTER		
70	ION 32 TOWNSHIP 17-S RANGE 35-E NMF	.w. (
THE E LINE, SECT	ONTOWNSHIP	
mmmmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3966' DF	Lea
		Other Data
16. Check	Appropriate Box To Indicate Nature of Notice, Report or	INT REPORT OF:
	NTENTION TO: SUBSEQUE	NI REPORT OF
IX I	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS CASING TEST AND CEMENT JOB	
PULL OR ALTER CASING	OTHER	
OTHER		
	Operations (Clearly state all pertinent details, and give pertinent dates, included	ling estimated date of starting any propose
17. Describe Proposed or Completed (work) SEE RULE 1103.	Sperations (Creary state are postment and	
	a 11 min momodial works	
We request permiss	ion to perform the following remedial work:	
1 Perforate	from $6340 - 6350 \text{ w/l-RASF jet shot per ft.}$	
2 Ica parts		•
Z. nog perio.	erfs. w/2000 gal. regular NE acid.	
5. Acidize pe	115. 4/2000 8-21 1-8-	
4. Test well.		
If unsuccessful:		
1. Set Cl Bri	idge plug @ 6330'	
2. Perf. from	n 6306 - 6315 w/l RASF jet shot per ft.	
7 Inc parts		
A Acidiza De	erfs. w/2000 gal. regular NE acid.	
4. ACIUIZO PO		
5. T est well	•	
- •		
If unsuccessful:		
•		
1. Set Cl Br	idge plug @ 6290'	
0 1011	1 back on production from original zone.	
18. I hereby certify that the informat	tion above is true and complete to the best of my knowledge and belief.	
	2	8-7-67
$\nu \prime \star$	Agent_	DATE 8-7-07
SIGNED	V E VY	

CONDITIONS OF APPROVAL.