**Bubmit 3 Copies** to Appropriate

## State of New Mexico

Form C-103 Energy, Minerals and Natural Resources Department District Office Revised 1-1-89 DISTRICTI OIL CONSERVATION DIVISION WELL API NO. P. O. Box 1980, Hobbs, NM 88240 P. O. Box 2088 30-025-02992 **DISTRICT II** Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease STATE FEE P.O. Drawer DD, Artesia, NM 88210 **DISTRICT III** 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 B = 1400SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK
TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" 7. Lease Name or Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: GAS OIL. Vacuum Abo Unit WELL [] WELL [X] **OTHER** 8. Well No. 2. Name of Operator Btrv 3. Phillips Petroleum Company 3. Address of Operator 9. Pool name or Wildcat 4001 Penbrook Street, Odessa, Texas Vacuum Abo Reef 4. Well Location 330 Feet From The south Line and 660 Feet From The 17-S 35-E 33 Range **NMPM** Lea County Section 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3945' RKB Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. **NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:** PERFORM REMEDIAL WORK REMEDIAL WORK PLUG AND ABANDON **ALTERING CASING TEMPORARILY ABANDON** COMMENCE DRILLING OPNS. **CHANGE PLANS** PLUG AND ABANDONMENT | | **PULL OR ALTER CASING** П CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1-04 thru 8862' PTD. MI & RU DDU. COOH with tubing, GIH with casing scraper. Cleaned 1-08-89: out to 8862'. WIH with CIBP set at 8550'. Spotted 5 bbls of acetic acid from 8550'-8250'. Perf'd 5-1/2" casing with 4" casing gun 2SPF from 8320'-8326'; 8341'-8358'; 1-09-89: 8378'-8390'; 8395'-8405'; 8408'-8412'; 8418'-8420'; 8428'-8442'; 8450'-8458'; 8466'-8484'. Acidized w/4550 gals 15% NEFE HCL containing corrosion inhibitor. Foam acid frac'd perfs 8320'-8484' w/5595 gals 15% NEFE HCL acid containing 8 gals SGA-HI, 5 gals HC-2, 10 gals FE-IA, 9 gals GE-2, 2 gals HAI-60/per 1000

SEE REVERSE SIDE I bereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Regulation & Proration **DATE** 3-01-89 Supervisor TELEPHONE NO. 915/367-1488 TYPE OR PRINT NAME Μ. Sanders (This space for State Use)

gals acid and 13,050 gals CO2 w/30# gelled crosslinked 10#brine and rock salt.

MAR 🕶 3 1989 ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT I SUPERVISOR

RECEIVED

MAR 2 1989

OCD HOBBS OFFICE

1-22-89: Pumped 24 hrs, 14 BO, 1402 BW. Well shut in prior to workover. Installed submersible pumping equipment and returned well to production.