Distribución de la		Form C-103
DISTRIBUTION		Supersedes Old
ANTA FE	NEWXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
S.G.S.	4	5g. Indicate Type of Lease
		State XX Fee
PERATOR		5. State Oil & Gas Lease No.
		B-1845
SUND	RY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR P USE "APPLIC	TION FOR PERMIT -** (FORM C-101) FOR SUCH PROPOSALS.)	
OIL X GAS		7. Unit Agreement Name
	0THER-	Vacuum Abo Unit
Philling Dot molecum (8. Farm or Lease Name Btry #3.
Phillips Petroleum (ompany	
Address of Operator		<u>Vacuum Abo Unit Tract 10</u> 9. Well No.
Room (11, Phillips H	ldg., Odessa, Texas 79761	
ocation of Well		10. Field and Pool, or Wildcat
UNIT LETTER K	1,980 FEET FROM THE SOUTH LINE AND 1,650	Vocum Abo Day 6
THE LINE, SECT	ON 34 17-S 35-E	
	RANGE	<u>— нмрм. Д////////////////////////////////////</u>
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	RKB 3934	
Check		Lea ANNIN
NOTICE OF I	Appropriate Box To Indicate Nature of Notice, Report	ort or Other Data
	SUB	SEQUENT REPORT OF:
FORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	(
PORARILY ABANDON		ALTERING CASING
L OR ALTER CASING	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
	CHANGE PLANS CASING TEST AND CEMENT JO	
OTHER .	OTHER	· []
OTHER	OTHER	
Describe Proposed or Completed O	OTHER	
Describe Proposed or Completed O work) SEE RULE 1103.		
	Derations (Clearly state all pertinent details, and give pertinent dates	
2-18-75: MI Johnson	Derations (Clearly state all pertinent details, and give pertinent dates	, including estimated date of starting any proposed
2-18-75: MI Johnson 2-19-75: Howco plug	Derations (Clearly state all pertinent details, and give pertinent dates WS Unit. Pld rods and tbg. ged back in same formation from 8 8071 to	, including estimated date of starting any proposed
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8	WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to tbg at 8,607', nkr at 8,602! Symbol 6 has	, including estimated date of starting any proposed 8,756' W/600# Hydromite.
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco trea	WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down thg thru csg perfs 8 700 6 700;	s, 55 BO, 20 BSW.
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco trea using 1 ba	WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to 'tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w//0 PW	s, 55 BO, 20 BSW.
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco trea using 1 ba Vacuum. Sw	Derations (Clearly state all pertinent derails, and give pertinent dates WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to 'tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs. 35 B0 / 8 PAW 40 DW	s, 55 BO, 20 BSW.
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco trea using 1 ba Vacuum. Sw 2-22/23-75: Shut down	Derations (Clearly state all pertinent details, and give pertinent dates WS Unit. Pld rods and tbg. gged back in same formation from 8,807' to 'tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs, 35 BO, 48 BAW, 40 BLW.	8,756' w/600# Hydromite. s, 55 BO, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco trea using 1 ba Vacuum. Sw 2-22/23-75: Shut down 2-24-75: Pld tbg &	WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs, 35 BO, 48 BAW, 40 BLW.	8,756' w/600# Hydromite. s, 55 BO, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco trea using 1 ba Vacuum. Sw 2-22/23-75: Shut down 2-24-75: Pld tbg & bottom, se	WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs, 35 BO, 48 BAW, 40 BLW. pkr. Set 2-3/8" tbg w/anchor catcher, tb ating nipple at 8,635!	8,756' w/600# Hydromite. s, 55 BO, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco trea using 1 ba Vacuum. Sw 2-22/23-75: Shut down 2-24-75: Pld tbg & bottom, se 2-25-75: Moved out	Derations (Clearly state all pertinent details, and give pertinent dates were were used by the state all pertinent details, and give pertinent dates a WS Unit. Pld rods and tbg. The state of the st	8,756' w/600# Hydromite. s, 55 BO, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco trea using 1 ba Vacuum. Sw 2-22/23-75: Shut down 2-24-75: Pld tbg & bottom, se 2-25-75: Moved out 2-26-75: P/24 hrs,	WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs, 35 BO, 48 BAW, 40 BLW. pkr. Set 2-3/8" tbg w/anchor catcher, tb ating nipple at 8,635'. Set pump at 8,63 unit, pmpd 22 hrs, no gauge. 155 BO. 85 BSW.	8,756' w/600# Hydromite. s, 55 BO, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco trea using 1 ba Vacuum. Sw 2-22/23-75: Shut down 2-24-75: Pld tbg & bottom, se 2-25-75: Moved out 2-26-75: P/24 hrs, 2-27-75: P/24 hrs.	WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to 'tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs, 35 BO, 48 BAW, 40 BLW. pkr. Set 2-3/8" tbg w/anchor catcher, tb ating nipple at 8,635'. Set pump at 8,63 unit, pmpd 22 hrs, no gauge. 155 BO, 85 BSW.	s, 756' w/600# Hydromite. s, 55 BO, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP g set at 8,638', with anchor on 5'.
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco trea using 1 ba Vacuum. Sw 2-22/23-75: Shut down 2-24-75: Pld tbg & bottom, se 2-25-75: Moved out 2-26-75: P/24 hrs, 2-27-75: P/24 hrs.	WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to 'tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs, 35 BO, 48 BAW, 40 BLW. pkr. Set 2-3/8" tbg w/anchor catcher, tb ating nipple at 8,635'. Set pump at 8,63 unit, pmpd 22 hrs, no gauge. 155 BO, 85 BSW.	s, 756' w/600# Hydromite. s, 55 BO, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP g set at 8,638', with anchor on 5'.
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco trea using 1 ba Vacuum. Sw 2-22/23-75: Shut down 2-24-75: Pld tbg & bottom, se 2-25-75: Moved out 2-26-75: P/24 hrs, 2-27-75: P/24 hrs.	WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs, 35 BO, 48 BAW, 40 BLW. pkr. Set 2-3/8" tbg w/anchor catcher, tb ating nipple at 8,635'. Set pump at 8,63 unit, pmpd 22 hrs, no gauge. 155 BO. 85 BSW.	s, 756' w/600# Hydromite. s, 55 BO, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP g set at 8,638', with anchor on 5'.
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco trea using 1 ba Vacuum. Sw 2-22/23-75: Shut down 2-24-75: Pld tbg & bottom, se 2-25-75: Moved out 2-26-75: P/24 hrs, 2-27-75: P/24 hrs, 2-28-75: P/24 hrs,	Derations (Clearly state all pertinent derails, and give pertinent dates a WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs, 35 BO, 48 BAW, 40 BLW. pkr. Set 2-3/8" tbg w/anchor catcher, tb ating nipple at 8,635'. Set pump at 8,63 unit, pmpd 22 hrs, no gauge. 155 BO, 85 BSW. 162 BO, 59 BSW. 190 BO, 50 BSW, GOR 710/1, from Abo perfs	<pre>s, including estimated date of starting any proposed 8,756' w/600# Hydromite. s, 55 B0, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP g set at 8,638', with anchor on 5'. 8,700-20'. Restored to production</pre>
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco trea using 1 ba Vacuum. Sw 2-22/23-75: Shut down 2-24-75: Pld tbg & bottom, se 2-25-75: Moved out 2-26-75: P/24 hrs, 2-27-75: P/24 hrs, 2-28-75: P/24 hrs,	Derations (Clearly state all pertinent details, and give pertinent dates WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to 'tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs, 35 BO, 48 BAW, 40 BLW. pkr. Set 2-3/8" tbg w/anchor catcher, tb ating nipple at 8,635'. Set pump at 8,63 unit, pmpd 22 hrs, no gauge. 155 BO, 85 BSW. 162 BO, 59 BSW. 190 BO, 50 BSW, GOR 710/1, from Abo perfs 5 900, 3,000# WP, double, w/one set pipe 2	<pre>s, including estimated date of starting any proposed 8,756' w/600# Hydromite. s, 55 B0, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP g set at 8,638', with anchor on 5'. 8,700-20'. Restored to production</pre>
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco trea using 1 ba Vacuum. Sw 2-22/23-75: Shut down 2-24-75: Pld tbg & bottom, se 2-25-75: Moved out 2-26-75: P/24 hrs, 2-27-75: P/24 hrs, 2-28-75: P/24 hrs,	WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to 'tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs, 35 BO, 48 BAW, 40 BLW. pkr. Set 2-3/8" tbg w/anchor catcher, tb ating nipple at 8,635'. Set pump at 8,63 unit, pmpd 22 hrs, no gauge. 155 BO, 85 BSW.	<pre>s, including estimated date of starting any proposed 8,756' w/600# Hydromite. s, 55 B0, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP g set at 8,638', with anchor on 5'. 8,700-20'. Restored to production</pre>
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco trea using 1 ba Vacuum. Sw 2-22/23-75: Shut down 2-24-75: Pld tbg & bottom, se 2-25-75: Moved out 2-26-75: P/24 hrs, 2-27-75: P/24 hrs, 2-28-75: P/24 hrs,	Derations (Clearly state all pertinent details, and give pertinent dates WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to 'tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs, 35 BO, 48 BAW, 40 BLW. pkr. Set 2-3/8" tbg w/anchor catcher, tb ating nipple at 8,635'. Set pump at 8,63 unit, pmpd 22 hrs, no gauge. 155 BO, 85 BSW. 162 BO, 59 BSW. 190 BO, 50 BSW, GOR 710/1, from Abo perfs 5 900, 3,000# WP, double, w/one set pipe 2	<pre>s, including estimated date of starting any proposed 8,756' w/600# Hydromite. s, 55 B0, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP g set at 8,638', with anchor on 5'. 8,700-20'. Restored to production</pre>
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco treas using 1 ba Vacuum. Sw 2-22/23-75: Shut down 2-24-75: Pld tbg & bottom, se 2-25-75: Moved out 2-26-75: P/24 hrs, 2-27-75: P/24 hrs, 2-28-75: P/24 hrs, 00P equipment: Serie Manual	Derations (Clearly state all pertinent details, and give pertinent dates WS Unit. Pld rods and tbg. rged back in same formation from 8,807' to tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs, 35 BO, 48 BAW, 40 BLW. pkr. Set 2-3/8" tbg w/anchor catcher, tb ating nipple at 8,635'. Set pump at 8,63 unit, pmpd 22 hrs, no gauge. 155 BO, 85 BSW. 162 BO, 59 BSW. 190 BO, 50 BSW, GOR 710/1, from Abo perfs a 900, 3,000# WP, double, w/one set pipe n Ly operated.	<pre>s, including estimated date of starting any proposed 8,756' w/600# Hydromite. s, 55 B0, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP g set at 8,638', with anchor on 5'. 8,700-20'. Restored to production</pre>
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco treas using 1 bay Vacuum. Sw 2-22/23-75: Shut down 2-24-75: Pld tbg & bottom, se 2-25-75: Moved out 2-26-75: P/24 hrs, 2-27-75: P/24 hrs, 2-28-75: P/24 hrs, 30P equipment: Serie Manual	Derations (Clearly state all pertinent details, and give pertinent dates WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to 'tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs, 35 BO, 48 BAW, 40 BLW. pkr. Set 2-3/8" tbg w/anchor catcher, tb ating nipple at 8,635'. Set pump at 8,63 unit, pmpd 22 hrs, no gauge. 155 BO, 85 BSW. 162 BO, 59 BSW. 190 BO, 50 BSW, GOR 710/1, from Abo perfs 5 900, 3,000# WP, double, w/one set pipe 2	<pre>s, including estimated date of starting any proposed 8,756' w/600# Hydromite. s, 55 B0, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP g set at 8,638', with anchor on 5'. 8,700-20'. Restored to production</pre>
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco treas using 1 bay Vacuum. Sw 2-22/23-75: Shut down 2-24-75: Pld tbg & bottom, se 2-25-75: Moved out 2-26-75: P/24 hrs, 2-27-75: P/24 hrs, 2-28-75: P/24 hrs, 30P equipment: Serie Manual	Perations (Clearly state all pertinent details, and give pertinent dates a WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to 'tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs, 35 BO, 48 BAW, 40 BLW. pkr. Set 2-3/8" tbg w/anchor catcher, tb ating nipple at 8,635'. Set pump at 8,63 unit, pmpd 22 hrs, no gauge. 155 BO, 85 BSW. 162 BO, 59 BSW. 190 BO, 50 BSW, GOR 710/1, from Abo perfs 5 900, 3,000# WP, double, w/one set pipe n thy operated.	<pre>s, including estimated date of starting any proposed 8,756' w/600# Hydromite. s, 55 B0, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP g set at 8,638', with anchor on 5'. 8,700-20'. Restored to production "ams and one set blind rams.</pre>
2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8 2-21-75: Runco treas using 1 bay Vacuum. Sw 2-22/23-75: Shut down 2-24-75: Pld tbg & bottom, se 2-25-75: Moved out 2-26-75: P/24 hrs, 2-27-75: P/24 hrs, 2-28-75: P/24 hrs, 30P equipment: Serie Manual	Derations (Clearly state all pertinent details, and give pertinent dates WS Unit. Pld rods and tbg. rged back in same formation from 8,807' to tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs, 35 BO, 48 BAW, 40 BLW. pkr. Set 2-3/8" tbg w/anchor catcher, tb ating nipple at 8,635'. Set pump at 8,63 unit, pmpd 22 hrs, no gauge. 155 BO, 85 BSW. 162 BO, 59 BSW. 190 BO, 50 BSW, GOR 710/1, from Abo perfs a 900, 3,000# WP, double, w/one set pipe n Ly operated.	<pre>s, including estimated date of starting any proposed 8,756' w/600# Hydromite. s, 55 B0, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP g set at 8,638', with anchor on 5'. 8,700-20'. Restored to production "ams and one set blind rams.</pre>
 2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8" 2-21-75: Runco treasusing 1 bay Vacuum. Sw 2-22/23-75: Shut down 2-24-75: Pld tbg & bottom, se 2-25-75: Moved out 2-26-75: P/24 hrs, 2-27-75: P/24 hrs, 2-28-75: P/24 hrs, 30P equipment: Serie Manual 	Perations (Clearly state all pertinent details, and give pertinent dates a WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to 'tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs, 35 BO, 48 BAW, 40 BLW. pkr. Set 2-3/8" tbg w/anchor catcher, tb ating nipple at 8,635'. Set pump at 8,63 unit, pmpd 22 hrs, no gauge. 155 BO, 85 BSW. 162 BO, 59 BSW. 190 BO, 50 BSW, GOR 710/1, from Abo perfs 5 900, 3,000# WP, double, w/one set pipe n thy operated.	8,756' w/600# Hydromite. s, 55 BO, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP g set at 8,638', with anchor on 5'. 8,700-20'. Restored to production ams and one set blind rams.
 2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8" 2-21-75: Runco treasusing 1 bay Vacuum. Sw 2-22/23-75: Shut down 2-24-75: Pld tbg & bottom, se 2-25-75: Moved out 2-26-75: P/24 hrs, 2-27-75: P/24 hrs, 2-28-75: P/24 hrs, 30P equipment: Serie Manual 	Perattons (Clearly state all pertinent details, and give pertinent dates a WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to 'tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs, 35 BO, 48 BAW, 40 BLW. pkr. Set 2-3/8" tbg w/anchor catcher, tb ating nipple at 8,635'. Set pump at 8,63 unit, pmpd 22 hrs, no gauge. 155 BO, 85 BSW. 162 BO, 59 BSW. 190 BO, 50 BSW, GOR 710/1, from Abo perfs s 900, 3,000# WP, double, w/one set pipe n Ly operated. w.J. Mueller	8,756' w/600# Hydromite. s, 55 BO, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP g set at 8,638', with anchor on 5'. 8,700-20'. Restored to production ams and one set blind rams.
 2-18-75: MI Johnson 2-19-75: Howco plug 2-20-75: Set 2-3/8" 2-21-75: Runco treasusing 1 bay Vacuum. Sw 2-22/23-75: Shut down 2-24-75: Pld tbg & bottom, se 2-25-75: Moved out 2-26-75: P/24 hrs, 2-27-75: P/24 hrs, 2-28-75: P/24 hrs, 30P equipment: Serie Manual 	Perations (Clearly state all pertinent details, and give pertinent dates a WS Unit. Pld rods and tbg. ged back in same formation from 8,807' to 'tbg at 8,607', pkr at 8,602'. Swbd 6 hr ted down tbg thru csg perfs 8,700-8,720' ll sealer per bbl. Flushed w/40 BW. Max bd 7 hrs, 35 BO, 48 BAW, 40 BLW. pkr. Set 2-3/8" tbg w/anchor catcher, tb ating nipple at 8,635'. Set pump at 8,63 unit, pmpd 22 hrs, no gauge. 155 BO, 85 BSW. 162 BO, 59 BSW. 190 BO, 50 BSW, GOR 710/1, from Abo perfs 5 900, 3,000# WP, double, w/one set pipe n thy operated.	8,756' w/600# Hydromite. s, 55 BO, 20 BSW. w/2,000 gals 15% NE HCL acid, press 2,900#, min 2,000#, ISDP g set at 8,638', with anchor on 5'. 8,700-20'. Restored to production ams and one set blind rams.