NO. OF COPIES RI	ECELVED.	7		,		
		-			Form C-103 Supersedes	
SANTA FE	A FE NEW MEXICO OLL CONSERVATION COMMISSION			C-102 and (		
FILE			CO OIL CONSE	RYATION COMMISSION	Effective 1	1-65
U.S.G.S.		-			5a. Indicate Ty	pe of Lease
LAND OFFICE		-			State XX	Fee
OPERATOR		-			5. State Oil &	
OF ERRICIA					o, endie off g	aus Leuse No.
[00.107.11	SUND	RY NOTICES AND	REPORTSION	WELLS .ck to a different reservoir. ( proposals.)		mmmmm
	USE THIS FORM FOR PI	ROPOSALS TO DRILL OR TO	DEEPEN OH PLUG BA	CK TO A DIFFERENT RESERVOIR. I PROPOSALS.)		
1. 011 VV	GAS				7. Unit Agreem	ent Name
WELL XX	WELL L_	OTHER.		· · · · · · · · · · · · · · · · · · ·		
2. Name of Operato	or				8, Farm or Lea	se Name
Mobil Oil Corporation						
3. Address of Operator						
Box 633, Midland, Texas 79701						
4. Location of Well						Pool, or Wildcat
UNIT LETTER C, 660 FEET FROM THE NORTH LINE AND 1980 FEET FROM						yburg San Andre
THE West LINE, SECTION 34 TOWNSHIP 17-S RANGE 35-E NMPM.						TITTITI III
THE Wes	t LINE, SECT	по 34 то	WNSHIP 17-S	84NGE 35-E	NMPM. ALLILL	
///////////////////////////////////////	///////////////////////////////////////	15. Elevatio	on (Show whether l	)F, RT, GR, etc.)	12. County	VIIIIIII
İMMM			<u>3939 GR</u>		Lea	
10.	Check	Appropriate Box 7	Fo Indicate Na	ature of Notice. Report	or Other Data	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
	<u> </u>					•
PERFORM REMEDIA	L WORK	PLUG /	ND ABANDON	REMEDIAL WORK	XX ALT	ERING CASING
TEMPORARILY ABAN	ID ON			COMMENCE DRILLING OPNS.	PLUG	AND ABANDONMENT
PULL OR ALTER CAS	SING	CHANG	E PLANS	CASING TEST AND CEMENT JOB		
				OTHER		
OTHER	·					
17. Describe Prop	osed or Completed C	Derations (Clearly state	all pertinent data	ils, and give pertinent dates, i	- 1. 1:	
work) SEE RU	LE 1103.		an perminent deta	is, and give periment dates, t	netating estimated date o	j starting any proposed
OBJ	ECTIVE: Set	t liner in open	hole, sele	ctively perf to re	duce water prod	
0/0/75						
8/8/75 4615 TD. MIRU X-Pert Well Serv unit 8/7/75. POH w/ rods, pump & tbg, ran 6迠 bit d						+ 11 All
					tog, ran 64 DI	τ on 14-4"
	DC's & 2-7/	/8 tbg to 4580,	pull bit t	.0 4200.		
0.40	14 * 1			···· · · · · · · · · · · · · · · · · ·	NI C 4500 460	2
8/9				irc in 6 hrs, CO C		
TP, rec frac sd & form, circ clean, pull bit to 4200, SD 1 hr, rerun bit to 4603,						
	no fillup,	pull bit to 42	00.			
	<b>.</b>					
8/11				DC's,ran 588'5" OD		
				4601, top of liner		
				lowco cmtd liner w/		
	containing	.3% CFR2, PD @	9 3 pm 8/9/7	'5, POH w/ 2-7/8 tb	og & liner setti	ng tool.
<b></b> -		A 44				
8/12	Ran 6½ bit	on $2 - 4\frac{1}{4}$ DC's	& 2-//8 th	og, tag cmt @ 3910,	, arill cmt to 4	UIS TOP OT
	5" liner, o	circ clean, tes	test csg & liner top w/ 1500#/30 min/ok, POH, ran 4½ bit on			
4 - 3-1/8 DC's & 2-7/8 tbg, drill cmt in top of 5" liner from 4013-4027, ran bit						
	to 4548, di	rill cmt to 457	b, circ cle	ean.	Louro	1
18. I hereby certify	that the information	n above is true and comp	lete to the best of	my knowledge and belief.	(OVER)	
$\hat{\boldsymbol{\rho}}$						
Chin	time 0 .	Jucker	۸	horized Agent	0 1	2_75
SIGNED	F. 3	-mar	<u>AU1</u>	norized Ayent	DATE	<u>)-/J</u>
	Crig, Signed	l b <del>j</del>				
APPROVED BY				· 6. (		
	PPROVAL, IF AND	Y :		· · · · · · · · · · · · · · · · · · ·	DATE	
		· •				

•

8/13 Schl ran BHC-N-Collar log from 2800-4575/3 hrs, SD to pick perfs.

 $\frac{\partial (\sigma_{1})}{\partial t} = \frac{\partial (\sigma_{1})}{\partial t} + \frac{\partial (\sigma_{1})}{\partial t} + \frac{\partial (\sigma_{2})}{\partial t} + \frac{\partial$ 

-

. .

1,31

Con any at

12. Sec. 56

····,

~ ~ ··

• •

and sharp a set of

noni

nt die CER

í

. ...

7169.7

.

· · · · ·

1.000 N

٠,

- 8/14 Ran bit to 4600, corrected PBTD, circ hole w/ clean SW, Howco spotted 300 gals 15% NEA, POH, Schl perf 5" liner in the SA @ 4390-94; 4404-08; 4427-34; 4438; 4441-44; 4446; 4450-60; 4463-80; & 4488-4492 w/ 1 JSPF, total of 58 holes, ran 5" RTTS pkr on 2-7/8 tbg to 4102.
- 8/15 Set pkr @ 4102, Dowell acidized SA perfs 4390-4492 w/ 5000 gals 28% NEA, used 60 RCNBS, TTP 1600, AIR 4.5 BPM, ISIP 1000, 2½ min on vac, job compl @ 9 am 8/14/75, SI 1 hr, POH, ran 2-7/8 tbg, OP to 4541, T. Perfs 4525-28, SN @ 4524, Guib TA set @ 3941 w/ 80CO# T, Total of 149 jts tbg, ran pump & rods, spaced out, started well to pmpg.

....

 $\mathbf{x} \in \mathcal{X}$ 

...

- 1

er everes

fo entrin in n

45

5 51 51

tan. An an an · · · · ·